CITYCAB PTE LTD **REPAIR ESTIMATE***

VEHICLE NO

SHC7958E

MAKE

REG.30.10.2020

20.04.20123

CHIANG/INCOME

IONIQ G3 MODEL

Qty	Parts Description/ Labour	Туре			Amount	
	REAR BUMPER < ^A			80	\$459.40	1
	REAR BUMPER SIDE BRACKET RH ? 🗡			\$55.80	\$55.80	XM
1	1 REAR BUMPER CENTRE MOULDING Ser				\$451.25	1
Y	1 REAR BUMPER REINFORCE MENT ? >				\$394.80	XIVIV
	1 REAR BUMPER REINFORCEMENT STAY LH ?丈				\$138.10	Xnv/
	1 REAR BUMPER REFLECTOR RH Se			200	\$41.45	1
1	O REAR BUMPER CLIPS INCC			\$2.20	\$22.00	1
	SUB TOTAL		974.10		\$1,562.80	
	20.00%		194.82		\$312.56	
	DISCOUNTED TOTAL		779.28		\$1,250.24	
	1 REAR REVERSE SENSOR 7 X (VIV				\$180.00 \$162.00	
	Labour Charge		A con-			1
	Panel Beating				350 \$600.00	1
	Spray Painting Charge		2		250\$300.00	
	Check Lighting / Wiring.		7		30 \$60.00	
	Remove/refix Reverse sensor				30 \$60.00	_
	TOTAL LABOUR				\$1,020.00	
				0		
	ESTIMATE TOTAL	20/0	1439 ·		\$2,432.24	4
		antum will	-			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					
	5 11C1.42					

2 days ~1150 gg

2114/23 3pm & Insu

LKK Auto Consultants hence notify the Repairer of the following: