

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST2300174
Date: 04 May 2023
Veh Reg No: GBF751K
Make/Model: TOYOTA DYNA 3.0
MANUAL
Chasis No: KDY2318024151
Reg. Date: 13/06/2016
Your Ref No: GQ10Z

Claim Type: Third Party
Accident Date: 29/04/2023

Estimate Repair Cost to Vehicle No :GBF751K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC FRT DOOR RH		
2	2 PCS FRT DOOR HINGE RH		
3	1 PC FRT DOOR CHECK RH		
4	1 PC FRT DOOR RUBBER RH		
5	1 PC FRT DOOR LOCK CHECKER RH		
6	1 PC FRT RH DOOR LOCK		
7	1 PC FRT DOOR LOCK OUTER PANEL RH		
8	1 PC FRT DOOR LOCK INNER PANEL RH		
9	1 PC FRT DOOR PILLAR RUBBER RH		
10	1 PC FRT DOOR OUTER HANDLE RH		
11	1 PC FRT DOOR KEY LOCK RH		
12	1 PC FRT DOOR OUTER MOULDING RH		
13	1 PC FRT DOOR FRAME MOULDING RH		
14	1 PC FRT DOOR GLASS RH		
15	1 PC FRT DOOR GLASS CHANNEL RH		
16	1 PC FRT DOOR CORNER GARNISH RH		
17	1 PC FRT DOOR CORNER INNER GARNISH RH		
18	1 PC FRT DOOR SIGNAL LAMP RH		
19	1 PC FRT DOOR TRIM RH		
20	1 PC FRT DOOR GLASS REGULATOR ASSY RH		
21	1 PC FRT DOOR INNER OPENER HANDLE ASSY RH		
22	1 PC FRT DOOR POWER WINDOW SWITCH ASSY RH		
23	1 PC FRT DOOR INNER RUBBER RH		
24	1 PC FRT DOOR COMPANY NAME STICKER		
25	1 PC FRT DOOR PILLAR OUTER RH		
26	1 PC FRT DOOR PILLAR INNER RH		
27	1 PC FRT DOOR SIDE MIRROR RH		
28	1 SET WIRE HARNESS		
29	1 PC WHEEL ARCH PANEL RH		
30	1 PC WHEEL ARCH PANEL TRIM RH		

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST2300174
Date: 04 May 2023
Veh Reg No: GBF751K
Make/Model: TOYOTA DYNA 3.0
MAMUAL
Chasis No: KDY2318024151
Reg. Date: 13/06/2016
Your Ref No: GQ10Z

Claim Type: Third Party
Accident Date: 29/04/2023

Estimate Repair Cost to Vehicle No :GBF751K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
31	1 PC MUDFLAP RH		
32	1 PC WHEEL ARCH HARD FENDER RH		
33	1 PC RH STEP GARNISH		
34	1 PC WHEEL ARCH PANEL RUBBER RH		
35	1 PC STEP PANEL RH		
36	1 PC FRT DOOR LH		
37	1 PC FRT DOOR HINGE LH		
38	1 PC FRT DOOR CHECK LH		
39	1 PC FRT DOOR RUBBER LH		
40	1 PC FRT LH DOOR LOCK		
41	1 PC FRT DOOR PILLAR RUBBER LH		
42	1 PC FRT DOOR OUTER MOULDING LH		
43	1 PC FRT DOOR FRAME MOULDING LH		
44	1 PC FRT DOOR GLASS CHANNEL LH		
45	1 PC FRT DOOR CORNER GARNISH LH		
46	1 PC FRT DOOR CORNER INNER GARNISH LH		
47	1 PC FRT DOOR SIGNAL LAMP LH		
48	1 PC FRT DOOR COMPANY NAME STICKER LH		
49	1 PC FRT DOOR REGULATOR ASSEMBLY LH		
50	1 PC FRT DOOR LOWER RUBBER LH		
51	1 PC FRT DOOR PILLAR OUTER LH		
52	1 PC FRT DOOR PILLAR INNER LH		
53	1 PC FRT DOOR TRIM LH		
54	1 PC WHEEL ARCH PANEL LH		
55	1 PC WHEEL ARCH PANEL TRIM LH		
56	1 PC WHEEL ARCH PANEL RUBBER LH		
57	1 PC WHEEL MUDFLAP LH		
58	1 PC STEP PANEL LH		
59	1 PC STEP PANEL GARNISH LH		
60	1 PC FRT WINDSCREEN GLASS		
61	1 PC FRT WINDSCREEN RUBBER		
62	2 PCS FRT WINDSCREEN GLASS SIDE TRIM		

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST2300174
Date: 04 May 2023
Veh Reg No: GBF751K
Make/Model: TOYOTA DYNA 3.0
MAMUAL
Chasis No: KDY2318024151
Reg. Date: 13/06/2016
Your Ref No: GQ10Z

Claim Type: Third Party
Accident Date: 29/04/2023

Estimate Repair Cost to Vehicle No :GBF751K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
63	1 PC FRT PANEL		
64	1 PC FRT PANELTOP PROTECTOR RH		
65	2 PCS FRT PANEL SIDE PROTECTOR		
66	1 PC FRT PANEL DYNA STICKER		
67	1 PC FRT TOP PANEL		
68	1 PC FRONT WIPER MOTOR		
69	1 PC FRT WIPER MOTOR LINK		
70	2 PCS FRT WIPER ARM		
71	2 PCS FRT WIPER BLADE		
72	2 PCS FRT WIPER NOZZLE		
73	2 PCS FRT PANEL SIDE GARNISH		
74	2 PCS FRT PANEL SIDE UPPER GARNISH		
75	1 PC FRT SIDE FENDER LH		
76	1 PC FRT SIDE FENDER RH		
77	1 PC FRT FLOOR PANEL		
78	1 PC FRT FLOOR PANEL MAT		
79	1 PC FRT GRILLE		
80	1 PC FRT GRILLE EMBLEM		
81	1 PC HEADLAMP RH		
82	1 PC HEADLAMP LH		
83	1 PC FRT BUMPER		
84	1 PC FRT BUMPER INNER FRAME CROSSMEMBER		
85	1 PC FRT FOG LAMP RH		
86	1 PC FRT FOG LAMP COVER RH		
87	1 PC FRT BUMPER BRACKET RH		
88	1 PC REAR SIDE GATE LH		
89	6 PCS REAR SIDE GATE HINGES LH		
90	1 PC DASHBOARD		
91	1 PC DASHBOARD REINFORCEMENT		
92	1 PC DASHBOARD GLOVEBOX COMPARTMENT		
93	1 PC DASHBOARD GLOVEBOX COVER		
94	1 PC DASHBOARD LOWER TRIM		

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST2300174
Date: 04 May 2023
Veh Reg No: GBF751K
Make/Model: TOYOTA DYNA 3.0
MAMUAL
Chasis No: KDY2318024151
Reg. Date: 13/06/2016
Your Ref No: GQ10Z

Claim Type: Third Party
Accident Date: 29/04/2023

Estimate Repair Cost to Vehicle No :GBF751K

Quantity		Description	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
95	1 PC	DASHBOARD CENTER BLACK COVER		
96	1 PC	DASHBOARD LOWER CENTER TRIM		
97	1 PC	FRT TYRE RIM RH		
98	1 PC	FRT TYRE RH		
99	1 PC	FRT SHOCK ABSORBER RH		
100	1 PC	FRT LOWER ARM RH		
101	1 PC	FRT TOP ARM RH		
102	1 PC	FRT TOP SIDE ARM RH		
103	1 PC	FRT KNUCKLE ARM RH		
104	1 PC	FRT WHEEL HUB RH		
105	1 PC	FRT WHEEL BEARING RH		
106	1 PC	FRT DISC BRAKE ROTOR RH		
107	1 PC	FRT DISC BRAKE ROTOR PANEL RH		
108	1 SET	FRT DISC BRAKE PEDAL RH		
109	1 PC	FRT DISC BRAKE CALIPER RH		
110	1 PC	FRT BRAKE PIPE RH		
111	1 PC	FRT BRAKE PIPE BRACKET RH		
112	1 PC	FRT BRAKE PUMP RH		
113	1 PC	ANTI ROLL BAR		
114	1 PC	ANTI ROLL BAR HOLDING LINKAGE		
115	1 PC	FRT CROSSMEMBER		
116	1 PC	FRT STEERING WHEEL		
117	1 PC	FRT STEERING SHAFT		
118	1 PC	FRT STEERING SHAFT HOUSING		
119	1 PC	FRT STEERING SHAFT COUPLING		
120	1 PC	FRT STEERING BOX		
121	1 PC	FRT STEERING TOP COVER		
122	1 PC	FRT STEERING BOTTOM COVER		
123	1 PC	FRT STEERING SHAFT LOWER COVER		
124	1 PC	FRT STEERING TIE ROD RH		
125	1 PC	FRT CROSSMEMBER MOUNTING		
126	1 PC	FRT AIR BOX		

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: **EST2300174**
Date: 04 May 2023
Veh Reg No: **GBF751K**
Make/Model: TOYOTA DYNA 3.0
MANUAL
Chasis No: KDY2318024151
Reg. Date: 13/06/2016
Your Ref No: GQ10Z

Claim Type: Third Party
Accident Date: 29/04/2023

Estimate Repair Cost to Vehicle No :GBF751K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
127	1 PC FRT AIR BOX PIPE LONG		
128	1 PC FRT AIR BOX PIPE SHORT		
129	1 PC RT AIR BOX SWITCH		
130	1 PC FRT BRAKE MASTER PUMP		
131	1 PC FRT BRAKE BOOSTER PUMP		
132	1 PC FRT BRAKE ACCELERATOR PEDAL ASSY		
133	1 PC FRT DRIVER SEAT ASSY		
134	1 PC FRT DRIVER SEAT ADJUST ROLLER		
135	1 PC AIRCON BLOWER		
136	1 PC AIRCON COOLING COIL ASSY		
137	1 PC DRIVER SEAT BELT		
138	1 PC DRIVER SEAT BELT TOP COVER		
139	1 PC DRIVER SEAT BELT BOTTOM COVER		
140	1 PC FRT CABIN REINFORCEMENT ABSORBER		
141	2 PCS FRT CABIN REINFORCEMENT MOUNTING		
142	4 PCS FRT BRAKE PIPE		
143	1 PC RADIATOR		
144	2 PCS ENGINE MOUNTING		
145	1 PC GEARBOX MOUNTING		
146	1 PC SIDE FUEL TANK RH		
147	2 PCS SIDE FUEL TANK HOLDING BRACKET RH		
148	1 PC AIR CLEANER BOX ASSY RH		
		0.00	0.00
Special Net			
149	1 SET FRT DOOR TRIM CLIPS RH		
150	1 SET WHEEL ARCH PANEL TRIM CLIPS RH		
151	1 PC FRT NUMBER PLATE		
152	1 SET WHEEL ARCH PANEL TRIM CLIPS LH		
153	1 SET FRT WINDSCREEN GLASS SIDE TRIM CLIP		
154	1 SET FRT PANELTOP PROTECTOR CLIPS		
155	1 SET FRT PANEL SIDE PROTECTOR CLIPS		

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST2300174
Date: 04 May 2023
Veh Reg No: GBF751K
Make/Model: TOYOTA DYNA 3.0
MAMUAL
Chasis No: KDY2318024151
Reg. Date: 13/06/2016
Your Ref No: GQ10Z

Claim Type: Third Party
Accident Date: 29/04/2023

Estimate Repair Cost to Vehicle No :GBF751K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
156	1 SET FRT GRILLE CLIPS		
157	1 PC BRAKE FLUID (4 LITRES)		
158	1 PC COOLANT (4 LITRES)		
		0.00	0.00
	Labour		
159	1 TO CHECK WIRING AND REPLACE DAMAGED WIRE	850.00	
160	1 TO REMOVE AND REFIT FRT WINDSCREEN GLASS	120.00	
161	1 TO REMOVE AND REFIT FRT OOR GLASS RH	100.00	
162	1 TO REMOVE AND REFIT FRT OOR GLASS LH	100.00	
163	1 TO REMOVE AND REFIT UPHOLSTERY	300.00	
164	1 TO REMOVE AND REFIT REAR WINDSCREEN GLASS	120.00	
165	1 TO REMOVE AND REFIT SEAT CUSHION	400.00	
166	1 TO REMOVE AND REFIT DASHBOARD	650.00	
167	1 TO REMOVE AND REFIT STEERING SHAFT	300.00	
168	1 TO REMOVE AND REFIT BRAKE MASTER PUMP	200.00	
169	1 TO REMOVE AND REFIT BRAKE BOOSTER PUMP	200.00	
170	1 TO REMOVE AND REFIT AIRCON BLOWER/AIRCON EVAPORATOR	400.00	
171	1 TO REMOVE AND REFIT AIRCON GAS	120.00	
172	1 TO REMOVE AND REFIT FRT UNDERCARRIAGE	800.00	
173	1 TO CHECK WHEEL ALIGNMENT	120.00	
174	1 TO REMOVE AND REFIT FRT CABIN AND REAR CARRIAGE	1,500.00	
175	1 TO SPRAY PANEL SEALANT	150.00	
176	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	3,500.00	
177	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	7,800.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST2300174
Date: 04 May 2023
Veh Reg No: GBF751K
Make/Model: TOYOTA DYNA 3.0
MAMUAL
Chasis No: KDY2318024151
Reg. Date: 13/06/2016
Your Ref No: GQ10Z

Claim Type: Third Party
Accident Date: 29/04/2023

Estimate Repair Cost to Vehicle No :GBF751K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
178	1 TO KNOCK AND REPAIR LH REAR TAILGATE LOWER PANEL AND WIRING	580.00	
		18,310.00	18,310.00
	Total		S\$ 18,310.00
	Add GST @ 8%		1,464.80
	Total Amount Payable		<u>S\$ 19,774.80</u>

TOTAL: SINGAPORE DOLLAR NINETEEN THOUSAND SEVEN HUNDRED SEVENTY FOUR AND CENTS EIGHTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE