

No	Parts Description	Qty	Unit Price	Total
1	Front bumper	1	\$440	\$440 <i>in</i>
2	LH front fender	1	\$490	\$490 <i>bf</i>
3	LH front door	1	\$980	\$980 <i>bt</i>
4	LH front door window regulator	1	\$240	\$240 <i>?</i>
5	LH sideskirt	1	\$390	\$390 <i>ky</i>
6	LH front wheel lining	1	\$150	\$150 <i>dl</i>
7	Clips brackets	8	\$11	\$88 <i>noy</i>
8	fender liner clip	6	\$2	\$12 <i>ny</i>
9	Front shock absorber	2	\$380 <i>RHX</i>	\$760 <i>LH?</i>
10	Lower arm	1	\$448	\$448 <i>?</i>
11	LH Headlamp	1	\$1,420	\$1,420 <i>?</i>
12	18" Sports Rim	1	\$600	\$600 <i>cul</i>
	Total			\$6,018

No	Labour Description	Qty	Unit Price	Total Price
1	Labour to repair and replaced damaged body parts	10	\$200	\$2,000
2	Labour to spray painting front bumper, LH fender, LH window arch, LH door (in and out) 4days	1	\$2,000	\$2,000
3	Wheel Alignment	2	\$120 80	\$240 160
4	Remove and install undercarriage parts	1	\$250	\$250 150?
5	Towing fees (from accident area to reporting center)	1	\$180	\$180 ? Towing receipt.
	Total			\$4,670

800

1000.

before / after report

photo.

Towing receipt.

Taylor 97495749 / 62503561

4/5/23 5 pm.

taylor@hants.com

06 days

2/5 Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: