

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 08 May 2023

Preliminary Advice

Vehicle No	: SBV7251G	Accident Date	: 02/05/2023
Make	: BMW 316I	Policy No.	: SP2002162708-01
Assignment Date	: 05/05/2023	Excess	: S\$500.00
Date of Inspection	: 08/05/2023	Est. Duration of Repair	: 4
Inspection At	: CITY AUTO PTE LTD (HQ) 160 SIN MING DRIVE #05-01,, SIN MING AUTOCITY, SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,765.40
Revised Amount	:S\$	4,054.40
Check Items (Estimated)	:S\$	7,264.50
Total	:S\$	11,318.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	25,354.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,646.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on lump sum basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.