

(001/113) web
ASS. REC. BY: gml

REF:

CS/GA123004641/R953

513 I

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SM2 8825T

at Workshop m/s TRANSURIKAS

of 27A, PANGOLAN PANGOLAN

Insured: GAI

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

12-30

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

328K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

REPAIR LIMIT - 217K

Veh No:

SM2 8825T

Yr Regn:

2021 / MAY

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

PORSCHE MACAN (1) POKER c.c. 1984

Colour:

BLUE

A/C:

Insured / Std / NI / NA

Sp. Reading

17112

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WP1222952ML B08265

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

265/40R21

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

14/03/23

D.O.I.

29/05/23

Survey held at

TRANSURIKAS

Des. of Damages: Frt: Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

REPAIR ESTIMATE

Name & Address:
Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY
 3 Temasek Avenue
 #16-01 Centennial Tower
 Singapore 039190

Vehicle No:
SMZ8825T

Brand & Model:
 Porsche Macan PDK

Chassis/VIN No:
WP1ZZZ95ZMLB08265

Date:
 25-Mar-23

Franchise:
 PORSCHE

Contact Person (Eurokars):
 LIM

Type of Claim:
THIRD PARTY

YEAR MODEL:
03/05/2021

WIP#: **43973**

Contact No (Eurokars):
 6331 0685

PARTS / MATERIAL CHARGES

MARK = Survey Marking (Key "A" if item is approved)

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER <i>de/</i>	P95B-807-417-L -G2X	1		-	\$ 1,226.00
2	TOWING COVER <i>de/</i>	P95B-807-500-A -G2X	1		-	\$ 50.00
3	REAR BUMPER LOWER SPOILER <i>de/</i>	P95B-807-521-AA-1E0	1		-	\$ 355.70
4	REAR BUMPER LOWER TRIM <i>de/</i>	P95B-807-834-K -1E0	1		-	\$ 237.20
5	BRACKET FOR REVERSE CAMERA <i>2X</i>	P95B-807-286-B -	1		-	\$ 16.40
6	SUPPORT FOR REVERSING CAMERA <i>2X</i>	P95B-807-997-B -1E0	1		-	\$ 23.00
7	SENSOR ?	P5Q0-919-275-B -G2X	4		-	\$ 1,120.80
8	SENSOR GASKET <i>n/</i>	P5Q0-919-133- -9B9	4		-	\$ 13.60
9	EXPANSION RIVET <i>n/</i>	PPAF-038-549- -	8		-	\$ 5.60
10	EXPANDER NUT <i>n/</i>	PN -908-214-01-	6		-	\$ 13.80
11	REAR BUMPER REINFORCEMENT ?	P8R0-807-313-D -	1		-	\$ 374.30
12	REINFORCEMENT BRACKET LH ?	P8R0-807-331-B -	1		-	\$ 140.20
13	REINFORCEMENT BRACKET RH ?	P8R0-807-332-E -	1		-	\$ 125.90
14	REAR BUMPER CENTER BRACKET ?	P95B-807-863-B -	1		-	\$ 137.50
15	REAR BUMPER RETAINER LH X	P95B-807-253-C -	1		-	\$ 89.20
16	REAR BUMPER RETAINER RH X	P95B-807-254-H -	1		-	\$ 124.80
17	BUMPER ABSORBER LH <i>ne/</i>	P95B-805-885- -	1		-	\$ 41.80
18	BUMPER ABSORBER RH <i>ne/</i>	P95B-805-886- -	1		-	\$ 41.80
19	REAR BUMPER BRACKET LH ?	P95B-807-571-B -	1		-	\$ 104.10
20	REAR BUMPER BRACKET RH ?	P95B-807-572-A -	1		-	\$ 104.10
21	TAILGATE <i>lt/</i>	P95B-827-041-EY-GRV	1		-	\$ 2,880.50
22	TAILGATE LOCK X	P95B-827-505-B -	1		-	\$ 754.20
23	CATCH BAR X	P7P0-827-517-F -	1		-	\$ 80.70
24	BLIND RIVET NUT <i>ne/</i>	PPAF-906-481- -	10		-	\$ 61.00
25	TAILGATE WEATHERSTRIP X	P95B-827-705-M -	1		-	\$ 298.50
26	RETAINING STRIP FOR UPPER SPOILER <i>ne/</i>	P95B-827-933- -	1		-	\$ 57.30
27	BLIND RIVET <i>ne/</i>	PPAF-016-206- -	10		-	\$ 71.00
28	SEAL <i>ne/</i>	P95B-827-359- -	1		-	\$ 132.60
29	DRAIN BUSH SPARE-WHEEL WEL <i>ne/</i>	P95B-502-899-00-	2		-	\$ 28.20
30	SEALANT (W736) <i>n/</i>	P000-043-305-32-	1		-	\$ 76.00
31	CLAMP FOR SUN VISOR <i>2X</i>	P95B-731-633-00-	2		-	\$ 17.20
32	P000-043-305-51-/CAVITY PRESERVATION (AK <i>n/</i>	PV04-015-001-AG-	1		-	\$ 76.90
33	LETTERING "MACAN" <i>n/</i>	P95B-853-675-F -	1		-	\$ 117.50

34	REAR WINDSCREEN MOULDING <i>no</i>	P95B-845-571- -	1	-	\$ 67.70
35	REFLECTOR LH <i>?</i>	P95B-945-725-AB-	1	-	\$ 348.10
36	REFLECTOR RH <i>?</i>	P95B-945-726-S -	1	-	\$ 348.10
37	EXHAUST PIPE CENTER <i>?</i>	P95B-253-487-GY-	1	-	\$ 1,562.60
38	CLAMPING SLEEVE EXHAUST SYSTEM <i>?</i>	P95B-111-220-20-	2	-	\$ 216.60
39	REAR SILENCER LH <i>?</i>	P95B-253-601- Y-	1	-	\$ 2,356.80
40	REAR MUFFLER RH <i>?</i>	P95B-253-612-DY-	1	-	\$ 1,961.50
41	TAILPIPE LH <i>assn</i>	P95B-253-681-AK-	1	-	\$ 1,601.10
42	TAIL PIPE RH <i>assn</i>	P95B-253-682-AG-	1	-	\$ 1,601.10
43	LENS-HEAD SCREW <i>no</i>	P9A7-008-019-00-	4	-	\$ 14.40
44					\$ -

Sub-Total (Parts Price) \$ - \$ 19,075.40

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE TAILGATE, REAR BUMPER, REINFORCEMENT & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR REAR END PANEL ALL AREAS AFFECTED BY THE ACCIDENT.	3120	\$ 6,240.00
2	TO RESPRAY TAILGATE, REAR BUMPER, REAR END PANEL	2400	\$ 3,700.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
4	TO SUPPLY REAR LICENCE PLATE WITH CASING <i>cu</i>	nett	\$ 70.00
5	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	nett	\$? 1,560.00
6	TO TRANSFER THE TAILGATE MECHANISM.	nett	\$ 780.00
7	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.	nett	\$ 560.00
8	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.	nett	\$ 195.00
9	TO TRANSFER THE REVERSE SENSORS.	nett	\$ 150 300.00
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
11	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 600.00
12	SUNDRIES.	nett	\$ 20 50.00

Survey Date & Time:	Repair Days:	Excess:
Surveyor Remarks:		

Sub-Total (Labour Price) \$ - \$ 14,555.00

	REVISED	PRICE
Parts Price	\$ -	\$ 19,075.40
Labour Price	\$ -	\$ 14,555.00
Total (Initial Estimate)	\$ -	\$ 33,630.40
Supp 1	\$ -	\$ -

REPAIR ESTIMATE

Supp 2	\$	-	\$	
Supp 3	\$	-	\$	
Total (Before Excess)	\$	-	\$	33,630.40
Less Excess	\$	-	\$	
TOTAL (After Excess)	\$	-	\$	33,630.40
GST	8%	\$	-	\$ 2,690.43
GRAND TOTAL		\$	-	\$ 36,320.83

Remarks:
 • This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
 • A fee of \$400 (excl GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair

Repair
Up 90010068
6 days
29/05/23
Resy before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	513I
Vehicle No.:	SMZ8825T
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2023
Vehicle Make:	PORSCHE
Vehicle Model:	MACAN II PDK E6
Primary Colour:	Blue
Manufacturing Year:	2021
Engine No.:	169118
Chassis No.:	WP1ZZZ95ZMLB08265
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$61,184.00
Original Registration Date:	03 May 2021
First Registration Date:	03 May 2021
Transfer Count:	0
Actual ARF Paid:	\$82,132.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 May 2031
PARF Rebate Amount:	\$61,599.00
COE Expiry Date:	02 May 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,190.00
COE Rebate Amount:	\$48,491.00
Total Rebate Amount:	\$110,090.00

The information contained herein is correct as at 29 May 2023

OK

Porsche Macan 2.0A PDK

\$328,000 Instalment \$2,832/mth

DIRECT OWNER

Apply for 2.28% loan

Shortlist

Paperwork Support

Only Aesthetics
30-min Instant Face Lifting

OPEN >

Overview Financial Photo Research

Depreciation	<i>i</i> \$35,880 / year
Reg. Date	31-May-2021 (7yrs 11mths 29days COE left)
Manufactured	<i>i</i> 2021
Mileage	15,000 km (7.5k / year)
Transmission	Auto
Engine Cap	1,984 cc
Road Tax	<i>i</i> \$1,194 / year
Power	185.0 kW (248 bhp) View specs of the Porsche Macan
Curb Weight	<i>i</i> 1,795 kg
COE	<i>i</i> \$58,089
OMV	<i>i</i> \$60,946
ARF	<i>i</i> \$81,703
Dereg Value	<i>i</i> \$107,764 as of today
No. of Owners	<i>i</i> 1