

(08/11/13) wef

ASS REC. BY: P. Bal

REF:

CS/H&B 2300 4646/Rip3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJC 9541Lat Workshop m/s MAJESTY AUTOMOTIVESof BANKER PARKWAY CRESCENT #03-25

Insured:

HSB

Policy No.

Class:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJC 9541L

Yr Regn:

/

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda 22

C.C.

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

138890

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMAK58504X 202678

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F:

205/45R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

06/05/23

D.O.I.

18/05/23

Survey held at

MAJESTYDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT -ESTIMATE REPAIR RANGE / NO. OF DAYS -

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$

)

S + RS SI



: Interview (\$

)

Photos



: Tech. Invs (\$

)

Others



: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

)