ASS. REC. BY MOVELS	(7/23004652/4Vp3)
, 5	ASSIGNMENT
From; Date:	Veh No: GBH 65682 Yr Regn: 03/08/1
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or (m /
To Inspect Vehicle No: GAH 6568	
at Workshop m/s C.1 Huse	Colour Scha A/C: Insured / Std / NI / NA
. 31 (/ 10-00	Solidar
of	Spirituality 1 2 3 3 7
Insured: 47232014	Eng/No:
Policy No. DMCVSNW00039332204	C/No: JTFAT35Y90K21105
Claims No. SNM23D201219/C02/TOHHS	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: (Nil) S/Rim / STD A/Rim or
	Tyre Size: F: /SS-NG
(Policy Condition)	R: 15-5-1212 keepsey
Remark: The veh had commenced its N/S	O/S BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: 8 70k.	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6/6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6/6 mm
Est. Repairs: 6 days Res.: Yes or No	D.O.A. 1 Vm/27 D.O.I. 5-/6/27
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
2011/00/11	
on the transfer to the transfe	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: I Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	The Gray Chapter Halle , Body Chapter a model and to comision
11	
8/27 2/5 8 5-100 informs	MN 6014 (red 7531.80, 59%)
13/0) /	
*	
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 6
Date/Time, File Pass to? : Preli. Report 1) : Final Report	Days Of Repair: 6 Resurvey No. of Trip: 2 Survey Fee:
. Field. Keport	
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: 2 Survey Fee:
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: 2 Survey Fee: Transportation:
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: 2 Survey Fee:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	
wner ID Type:	Company
wner ID: ehicle Details	784W
ehicle No.:	GBH6568Z
ehicle to be Exported:	No
tended Deregistration Date:	05 May 2023
ehicle Make:	TOYOTA
ehicle Model:	DYNA 150 5MT
rimary Colour:	Silver
lanufacturing Year:	2018
ngine No.:	1KD2812423
hassis No.:	JTFAT35Y90K211057
laximum Power Output:	-
pen Market Value:	\$27,084.00
riginal Registration Date:	03 Aug 2018
rst Registration Date:	03 Aug 2018
ransfer Count:	1
ctual ARF Paid: ntended PARF Rebate Details	\$1,355.00
ARF Eligibility:	No
ARF Eligibility Expiry Date:	-
ARF Rebate Amount: Itended COE Rebate Details	\$0.00
OE Expiry Date:	02 Aug 2028
OE Category:	C - Goods Vehicle & Bus
OE Period(Years):	10
QP Paid:	\$26,609.00
OE Rebate Amount:	\$13,948.00
otal Rebate Amount:	\$13,948.00

The information contained herein is correct as at 05 May 2023

OK

sgcarmart

Post an Ad



New Cars Used Cars Car Loan Rental Cars Sell Cars Directory Products Insurance Articles Forum

> Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD!

> > Ways of Selling

Advertiser Login

Affordable, Jan16 Vw Sportsvan, 32mths Left, @\$50k.



Immaculate Cond, Groom & Wash Regularly. Hassle Free Driving For U & Ur Family. Direct Owner StarAd







Sienta Hybrid: Living big in a tiny house

In its third-generation, the visually reinvented Sienta is still as generous and versatile with its space, but packs a few pleasant surprises up its sleeves. Read this article



Toyota Dyna 150 3.0M \$78,800 \$14,750 /yr 06-Sep-2018 2,982 cc Truck Available Fuel Type: Diesel

Excellent condition unit. first come first serve. full canopy, only 1 owner, Regularly serviced and maintained, well taken care. new fresh...

SG Motor Link Pte Ltd

Posted: 03-May-2023



Toyota Dyna 150 3.0M \$76,800 \$15,100 /yr 04-Jun-2018 2,982 cc Truck Available

Fuel Type: Diesel

One owner. Very good condition. With box. High trade in welcome price negotiable. Call now for viewing and test drive.

ABWIN (1994) Pte Ltd Posted: 03-May-2023

SS37232D0002 / Success United Pte Ltd ENTRY DATE & TIME: 13/02/2023 18:32 (SGT) SUBMITTED BY: Elise Law Yi Ting VERSION: 1 (13/02/2023 18:32 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 13/02/2023 18:32 (SGT) Reported by Date of Accident 12/02/2023 17:40 (SGT) Exact Location of Accident Near 14 Mandai Estate, Singapore

Additional Location Information MANDAI ESTATE

Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number **GBH6568Z**

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner ACROMEC ENGINEERS PTE LTD Company Reg No 1XXXXX784W Email Address ZOE.TAN@ACROMEC.COM Mobile Phone No (Phone) +65-97908782

VEHICLE PARTICULARS

Alternative Phone No.

Manufacturer Toyota Model Dyna

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

CC

No - Reporting only Commercial vehicle

Employment

Auto 2982

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number

Allianz Insurance Singapore Pte. Ltd. SP2002482895

DRIVER

Name of Driver Passport No/FIN Date Of Birth Occupation

BAPPY MOHAMMAD GXXXX212X 12/02/1994 Indoor

Date Of Driving Pass 19/05/2021 Driving experience 1 YEAR AND 9 MONTHS Gender Mobile Number (Phone) +65-85788632 Alt. Phone Number Email Address BAPPYALI311@GMAIL.COM Address 500 OLD CHAO CHU KANG ROAD S 698924 Address complement Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Employee Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Raining Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 UNKNOWN Gender Male PASSENGER 2 UNKNOWN Name Gender Male PASSENGER 3 UNKNOWN Gender Male PASSENGER 4 Name UNKNOWN Gender Male PASSENGER 5 Name UNKNOWN Gender Male PASSENGER 6 UNKNOWN Gender Male PASSENGER 7 UNKNOWN Male

PASSENGER 8 Name UNKNOWN Gender Male PASSENGER 9 UNKNOWN Gender Male PASSENGER 10 UNKNOWN Gender Male PASSENGER 11 Name UNKNOWN Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?

Yes
Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP2320H Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Goods vehicle Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder ansior the Actual Driver.
- Information provided must be as truthful and incurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that opper of this report will for a fee be made available upon application by interested parties.
- By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") maytare permitted to collect, use, disclose another process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(1) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:

(ii) investigating the accident and/or my daims:

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about the to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, mey/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law from), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (d driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

law ti Ing

Sketch Plan

Voh A: GBH 05682

With B: 40 2320 H

Peth C: Unknown (B46)

Describe Circumstance of the Accident
Do the above said dute and time it was rainly heavily. I was driving along
Mondal State and the relicle infront (veh 8: YP 2320H) Storped Suddenly.
I also stop my reh creh 1: GBH 6568 Z) also. All of a suddenly reh B
Start to there his reh and I immediate homed him. However he
couldn't step in time and reversed into the front portion of my ret cause
damaging my reh. The driver of reh & admitted that he reversed
damaging my reh. The driver of reh a admitted that he reversed his reh because there is a bus infront of his reh that wish to reverse.
He also montioned that when he seversed his net into mine, he did
not see my wh.
Alease note that I do have a in-ear camera but the Vidao was
over-written with newer rideo that was recorded after the accident.
I am not aware that the video camera sim and is only 195.

Decigration I/We decign the foregoing particulars are true in every respect

Witnessed by Reporting Censer Personnel (Name as in NR/C/C) card)

SIN HWEE MOTOR PTD LTD

BLK 3023A UBI RD 1 #01-59 SINGAPORE 408717

UEN: 201327079M

Estimate

Date	Estimate #	
4/5/2023	1032	

Name / Addre	ss	
ACROMEC ENG	INEERS PTE LTD	

Not Authoral
nevery
5-15/23
2/585100/
d/s85100/
Taluphe. Herry-

VEHICLE NO	MODEL	
GBH 6568 Z	DYNA	

WINDSCREEN RUBBER 295.48 WIPER ARM CAP 38.77 WIPER PANEL 3uf FRONT PANEL 3olson 1,144.90	295.48 38.77 468.12 - 1,144.90 581.79 - 358.97
WIPER ARM CAP WIPER PANEL 38.77 468.12	468.12 - 1,144.90 - 581.79 -
WIPER PANEL 3 ut	1,144.90 · 581.79 ·
FRONT PANEL Roller 1,144.90	581.79
CENTER GRILLE en 581.79	358.97
R/H SIDE FENDER 358.97	
SIDE MIRROR ASSY Ben 606.48	606.48 -
DYNA LOGO (1/C)	38.00-
CENTER LOGO 98.03	98.05 -
FRONT HEADLAMP 1,145.79	2,291.58
SUBTOTAL 2 (C2)	5,922.14
-588.14	-588.14
TO DISMOUNT AND MOUNT FRONT WINDSCREEN TO FACILITATE REPAIR 200.00	200.00
WORK	
TO DISMOUNT AND MOUNT DASHBOARD TO FACILITATE REPAIR WORK 550.00	550.00
TO RESTORE FRONT PANEL AND WIPER PANEL INCLUDE KNOCKING AND 2,200.00	2,200.00
WELDING	
TO ALIGN FRONT R/H DOOR INCLUDE JACKING AND PULLING	
TO REPLACE AND INSTALL ABOVE ITEMS	
TO SPRAY PAINT FRONT PANEL, WIPER PANEL, SIDE FENDER, GRILLE AND 1,500.00	1,500.00
BUMPER	
TO CAPPAY OUT WITH CHECKING AND TROTHIG	00.00
TO CARRY OUT WIRE CHECKING AND TESTING 80.00	80.00
TO SUPPLY AND TUFF KOTE 80.00	80.00
TO REMOVE AND REFIX AIR CON SYSTEM TO FACILITATE REPAIR WORK 250.00	250.00
TO SUPPLY AND TOP UP AIR CON GAS	20.00
LKK Auto Consultants hence notify	
the Repairer of the following:	
◆ To resum by bafore/after spray painting	20171
We display damaged parties dening resurvey P = 4	180.20
Parts prices are subject to confination	152
Third party survey is on a "Without Prejudica" basis	4336.27
No illegal modification(s) is allowed	211.
a:Supplementary Item(s) must be resurreged and is subject to final approval from insurance Company.	6100

Acknowledged by Repairer Singature: Total

\$10,194.00

SIN HWEE MOTOR PTD LTD

BLK 3023A UBI RD 1 #01-59 SINGAPORE 408717 UEN: 201327079M

Estimate

Total

Date	Estimate #		
9/5/2023	1034		

Name / A	ddress				
ACROMEC	ENGINE	RS PTI	LID		S.J.

	Description	QI QI
GBH 6568 Z	DYNA	
VEHICLE NO	MODEL	

********* SUPPLEMENTARY *********			
WASHER TANK AIR CON UNIT PANEL INNER BRACKET TO REPLACE AND INSTALL ABOVE TEMS A	252	221.50 1,920.10 46.20	221.50 1,920.10 46.20
TO REPLACE AND INSTALL ABOVE ITEMS TO SUPPLY AND TOP UP AIR CON GAS Replace A profit		250.00	250.00 X
			ANNALIS ANNALI

Total

\$2,437.80