

Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street #01-60, Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	P000034421	Date of Loss:	01/04/2023
Vehicle Reg. No.:	SMW2871P	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KAVITA D/O KATHERBIL		
Driver:	DANIEL		

Make/Model:	MAZDA 3, 1.5 4 DOOR SEDAN SP (A)	Vehicle Reg. Date:	31/05/2016
Vehicle Colour:	BLACK		
Engine No:	P520352621	Chassis No:	JM6BM42A8G0335434
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	14

Remarks:	VEHICLE WAS TOWED TO TP COMPOUND AFTER INCIDENT.
Present Location:	CHENG AUTO BODYWORKS (HQ)

COST OF CLAIMS**Amount**

Parts	6,715.50
Miscellaneous Items	1,010.00
Labour	1,800.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	9,525.50
- Excess (S\$)	3,000.00
(S\$)	6,525.50
+ GST 8.00% (S\$)	522.04
Nett Amount (S\$)	7,047.54

This claim is handled by: LAI JIA WEN RACHEL*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 08 May 2023)**Parts:** 143 MAZDA 3 1.5 4 DOOR SEDAN SP (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Auto Bodyworks/SMW2871P/08/05/2023 10:52**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	*880.00 F
2	1		*BONNET HINGE RH	0.00	0.00	*35.00 F
3	1		*BONNET HINGE LH	0.00	0.00	*35.00 F
4	1		*HEADLAMP LH	0.00	0.00	*1,450.00 F
5	1		*FENDER FRT LH	0.00	0.00	*185.00 F
6	1		*DOOR FRT LH	0.00	0.00	*680.00 F
7	1		*DOOR HINGE UPPER FRT LH	0.00	0.00	*35.00 F
8	1		*DOOR HINGE LOWER FRT LH	0.00	0.00	*40.00 F
9	1		*FENDER INNER SHIELD COVER FRT LH	0.00	0.00	*75.00 F
10	1		*COUPLE STARTER ASSY	0.00	0.00	*1,600.00 F
11	1		*FRT BUMPER	0.00	0.00	*550.00 F
12	1		*BUMPER RETAINER RH	0.00	0.00	*15.00 F
13	1		*BUMPER RETAINER LH	0.00	0.00	*15.00 F
14	1		*FOGLAMP LH	0.00	0.00	*155.00 F
15	1		*FOGLAMP COVER LH	0.00	0.00	*35.00 F
16	1		*BUMPER LOWER SIGNAL LAMP LH	0.00	0.00	*95.00 F
17	1		*HEADLAMP WASHER SPINTER LH AASY	0.00	0.00	*170.00 F
18	1		*BUMPER WASHER COVER LH	0.00	0.00	*55.00 F

F=Franchise part.

Sub Total (\$\$)	6,105.00
+ Margin on L,N Items 10.00% (\$\$)	610.50
Total Parts (\$\$)	6,715.50

Cheng Auto Bodyworks/SMW2871P/08/05/2023 10:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	BUMPER CLIPS	80.00
2	1	FENDER CLIPS	80.00
3	1	RIM FRONT LH	600.00
4	1	TYRE	250.00
Sub Total (S\$)			1,010.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR	New	800.00
2	SPRAYPAINTING	New	800.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	100.00
4	ALIGNMENT	New	100.00
Gross Labour Cost (S\$)			1,800.00

Cheng Auto Bodyworks/SMW2871P/08/05/2023 10:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >