

Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street #01-60, Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	P000034421	Date of Loss:	01/04/2023
Vehicle Reg. No.:	SMW2871P	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KAVITA D/O KATHERBIL		
Driver:	DANIEL		
Make/Model:	MAZDA 3, 1.5 4 DOOR SEDAN SP (A)	Vehicle Reg. Date:	31/05/2016
Vehicle Colour:	BLACK		
Engine No:	P520352621	Chassis No:	JM6BM42A8G0335434
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14 6		
Remarks:	VEHICLE WAS TOWED TO TP COMPOUND AFTER INCIDENT.		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS	Amount
Parts	6,715.50
Miscellaneous Items	1,010.00
Labour	1,800.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	9,525.50
- Excess (S\$)	3,000.00
(S\$)	6,525.50
+ GST 8.00% (S\$)	522.04
Nett Amount (S\$)	7,047.54

This claim is handled by: LAI JIA WEN RACHEL

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 08 May 2023)**Parts:** 143 MAZDA 3 1.5 4 DOOR SEDAN SP (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Auto Bodyworks/SMW2871P/08/05/2023 10:52**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	✓880.00 F BUC
2	1		*BONNET HINGE RH	0.00	0.00	*35.00 F X NN
3	1		*BONNET HINGE LH	0.00	0.00	*35.00 F X R
4	1		*HEADLAMP LH	0.00	0.00	✓1,450.00 F CRA
5	1		*FENDER FRT LH	0.00	0.00	✓185.00 F BUC
6	1		*DOOR FRT LH	0.00	0.00	✓680.00 F BUC
7	1		*DOOR HINGE UPPER FRT LH	0.00	0.00	*35.00 F XSVC
8	1		*DOOR HINGE LOWER FRT LH	0.00	0.00	*40.00 F XSVC
9	1		*FENDER INNER SHIELD COVER FRT LH	0.00	0.00	✓75.00 F CRA
10	1		*COUPLE STARTER ASSY — take photo after dismantle.	0.00	0.00	✓1,600.00 F CRA
11	1		*FRT BUMPER	0.00	0.00	✓550.00 F BR
12	1		*BUMPER RETAINER RH	0.00	0.00	*15.00 F ? NN
13	1		*BUMPER RETAINER LH	0.00	0.00	✓15.00 F CRA
14	1		*FOGLAMP LH	0.00	0.00	*155.00 F ? NN
15	1		*FOGLAMP COVER LH	0.00	0.00	✓35.00 F MIS
16	1		*BUMPER LOWER SIGNAL LAMP LH	0.00	0.00	*95.00 F ? NN
17	1		*HEADLAMP WASHER SPINTER LH AASY	0.00	0.00	✓170.00 F CRA
18	1		*BUMPER WASHER COVER LH	0.00	0.00	✓55.00 F MIS

F=Franchise part.

Sub Total (S\$)	6,105.00
+ Margin on L,N Items 10.00% (S\$)	610.50
Total Parts (S\$)	6,715.50

Cheng Auto Bodyworks/SMW2871P/08/05/2023 10:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	BUMPER CLIPS	80.00 SD NEC
2	1	FENDER CLIPS	80.00 30 NEC
3	1	RIM FRONT LH	600.00 XR
4	1	TYRE	250.00 XNN
Sub Total (\$\$)			1,010.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR	New	800.00 600
2	SPRAYPAINTING	New	800.00 ✓
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	100.00 60
4	ALIGNMENT	New	100.00 60
Gross Labour Cost (\$\$)			1,800.00

Cheng Auto Bodyworks/SMW2871P/08/05/2023 10:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Not authorise
- Excess = \$
- Resurvey before paint for P/P repair.
- Survey by Simon Ho (LKK) (6256 3561)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

(SUPPLEMENTARY)

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	P000034421	Date of Loss:	01/04/2023
Vehicle Reg. No.:	SMW2871P	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KAVITA D/O KATHERBIL		
Driver:	DANIEL		
Make/Model:	MAZDA 3, 1.5 4 DOOR SEDAN SP (A)	Vehicle Reg. Date:	31/05/2016
Vehicle Colour:	Black		
Engine No:	P520352621	Chassis No:	JM6BM42A8G0335434
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS	Amount
Parts	1,628.00
Miscellaneous Items	0.00
Labour	1,200.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,828.00
+ GST 8.00% (S\$)	226.24
Nett Amount (S\$)	3,054.24
+ Previous Estimates (S\$)	7,047.54
Claim Total (S\$)	10,101.78

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 May 2023)

Parts: 143 MAZDA 3 1.5 4 DOOR SEDAN SP (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Auto Bodyworks/SMW2871P/18/05/2023 09:35

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR FENDER LH	0.00	0.00	DD(NC) 900.00 F
2	1		*REAR BUMPER	0.00	0.00	DD(NC) *580.00 F
Sub Total (\$\$)						1,480.00
+ Margin on L,N Items 10.00% (\$\$)						148.00
Total Parts (\$\$)						1,628.00

F=Franchise part.

Cheng Auto Bodyworks/SMW2871P/18/05/2023 09:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR	New	600.00
2	SPRAYPAINT	New	600.00
Gross Labour Cost (\$\$)			1,200.00

Cheng Auto Bodyworks/SMW2871P/18/05/2023 09:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

> Back to OneMotoring

D.O.A. : 1/4/2023
Bal. : 3yrs 2mths.
M.V. : \$47,000.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	921I
Vehicle Details	
Vehicle No.:	SMW2871P
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2023
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	P520352621
Chassis No.:	JM6BM42A8G0335434
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,539.00
Original Registration Date:	31 May 2016
First Registration Date:	31 May 2016
Transfer Count:	②
Actual ARF Paid:	\$13,539.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2026
PARF Rebate Amount:	\$8,800.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$49,700.00
COE Rebate Amount:	\$14,270.00
Total Rebate Amount:	\$23,070.00

The information contained herein is correct as at 09 May 2023

OK

13,610

13,570