

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 11 May 2023

Preliminary Advice

Vehicle No	: SMW2871P	Accident Date	: 01/04/2023
Make	: MAZDA 3	Policy No.	: P000034421
Assignment Date	: 08/05/2023	Excess	: S\$3,000.00
Date of Inspection	: 09/05/2023	Est. Duration of Repair	: 6
Inspection At	: CHENG AUTO BODYWORKS (HQ) 5 SOON LEE STREET #01-60, PIONEER POINT SINGAPORE 627607		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,525.50
Revised Amount	:S\$	7,864.50
Check Items (Estimated)	:S\$	291.50
Total	:S\$	8,156.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	47,000.00
COE / PARF Rebate	:S\$	23,070.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,930.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :the vehicle repair on part by parts basis,due to no second hand parts available. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.