

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Affiliated to Federation Internationale Des Experts En Automobile					
	HSBC LIFE (SINGA	APORE) PTE LTD	Ref:	CS3/HSB23004658/Wvp3	
	10 MARINA BOULE #48-01 MARINA BA 2SINGAPORE 0189	AY FINANCIAL CENTRE TOWER	Date:	08/05/2023	
			Code:	HSB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SH 7747R	Veh. Inspected	SND 6839X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	S3M04MC1	Excess (\$)	0.00	
	Assign From	LOW GARNET	Assign Date	08/05/2023	
2. Vehicle Particulars & Condition					
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
5.	General Information				
	Accident Date	07/05/2023	Inspection Date	09/05/2023	
	Survey held at	HIAP LEK AUTOMOBILE TRADI	NG		
	160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722				
5a.	a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				