



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Lumens Pte. Ltd 22 Sin Ming Lane #01-74 Midview City Singapore 573969 Mcbile: 83221830			
			Document No.					
			0					
			Document Date					
			04/05/2023					

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	ZVW40R	AWXEBW Q4	18/08/2022	SNG5595P	0	21682	72/DS/SNG5595P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU40J068245	2ZR2N29966	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: TP VEH:SHB5576S DATE OF ACC:28.04.2023 TOW IN:29.04.2023				50 100.00
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				198.00
3	B	BP-LAB2 CHECK WIRING SYSTEM				134.64
4	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				396.00
5	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
6	B	BP-LAB2 REPLACE ACC DAMAGED PARTS				2376.00
7	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				1968.00
8	1	TREVSE-47006 43 BACK SENSOR 218 ATTITUDE BLACK	1.00	101.05		101.05
9	2	T52159-47912 COVER, RR BUMPER	1.00	702.60		702.60
10	3	S52161-0K040 PIECE, RR BUMPER	10.00	5.10		51.00
11	4	T76891-47040 SPOILER, RR NO.1	1.00	1069.20		1069.20
12	5	T52155-47010 SUPPORT, RR BUMPER	1.00	179.80		179.80
13	6	T52575-47030 RETAINER, RR BUMPER	1.00	74.30		74.30
14	7	T52156-47010 SUPPORT, RR BUMPER	1.00	179.80		179.80
15	8	T52576-47030 RETAINER, RR BUMPER	1.00	74.30		74.30
16	9	T52023-12240 REINFORCEMENT	1.00	273.70		273.70
17	0	T52015-47080 ARM SUB-ASSY, RR	1.00	221.30		221.30

For & on behalf of		Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd				
		Please acknowledge receipt of vehicle	Parts	Less Amount Due
			Labour	
			Sublet	
			Lubrication/Fluid	
			Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Lumens Pte. Ltd 22 Sin Ming Lane #01-74 Midview City Singapore 573969 Mobile: 83221830
	Document No. 0	
	Document Date 04/05/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	ZVW40R	AWXEBW Q4	18/08/2022	SNG5595P	0	21682	72/DS/SNG5595P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZS3EU40J068245	2ZR2N29966	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
18	1	T52016-47060 ARM SUB-ASSY, RR <i>3x11</i>	1.00	221.30		221.30

*Repair
Hp 60000068
3 days
08/05/23 P1500
Remy 64 paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 8,518.99
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	GST 8.00% 681.52
		3,148.35 5,370.64 0.00 0.00 0.00	Less 0.00
			Amount Due 9,200.51

Customer Copy