Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: 12 May 2023 Richard Ang Wei Guang Date:

Preliminary Advice

Insured Vehicle No : FBG7182B

TP Vehicle No : 04/05/2023 : SLT851M Accident Date Make : TOYOTA C-HR HYBRID Assignment Date : 10/05/2023

Date of Inspection : 09/05/2023 Est. Duration of Repair : 4

: LIAN HER MOTORS Inspection At

BLK 5038 ANG MO KIO INDUSTRIAL PARK 2,

#01-405 SINGAPORE 569541.

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,760.65	
Revised Amount	:S\$	3,232.32	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	3,232.32	
Lump Sum Repair	·S\$	2 600 00	

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 84,000.00 COE / PARF Rebate :S\$ 24,799.00

Salvage Value :S\$

Margin for Repair :S\$ 59,201.00

Remarks

()	The vehicle is economical for repair
()	The vehicle is not economical for repair
()	Part-by-Part repair
(Χ)	Lump Sum repair

The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (x) (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.