



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883

Company & GST Registration No : 201828067M

TP Budget Direct
Veron

VEHICLE INSPECTION ESTIMATE

M/S : AUTO & GENERAL INSURANCE (SINGAPORE)
(MOTOR CLAIM DEPARTMENT)

Email claims@budgetdirect.com.sg

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No: SJE228R Date:
Vehicle Model: HYUNDAI STARIA Reg. Date: 17.04.2023
Chassis No: KMHYF814MPU096001 D.O.A: 03.05.2023

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Front Grille <i>new</i>	1	\$ 1,607.10	\$ 1,607.10	<i>+</i>
2	Front Grille - Black <i>at</i>	1	\$ 438.20	\$ 438.20	<i>✓</i>
3	Front Number Plate Garnish <i>new</i>	1	\$ 43.50	\$ 43.50	<i>x</i>
4	Front Bumper Sensor <i>new</i>	2	\$ 183.60	\$ 367.20	<i>+</i>

Total For List Items: \$ 2,456.00

Less Spare Parts Discount (20%): \$ 491.20

Total: \$ 1,964.80

SPECIAL NETT ITEMS

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Front Number Plate W Casing <i>at</i>	1	\$ 60.00	\$ 60.00	<i>30-</i>
2	Front Bumper Clips 1set <i>new</i>	1	\$ 30.00	\$ 30.00	<i>✓</i>

Total For S/N Items: \$ 90.00

LABOUR

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	To panel beat/straighten/realign accident affected areas	1	\$ 800.00	\$ 800.00	<i>250</i>
2	To spray paint on affected areas	1	\$ 800.00	\$ 800.00	<i>x 150</i>
3	To check and realign headlamp and focus	1	\$ 60.00	\$ 60.00	<i>x</i>

Total For Labour: \$ 1,660.00

Grand Total: \$ 3,714.80

- LKK Auto Consultants hence notify the Repairer
- To resurvey before and after spray painting
 - To display damaged parts during resurvey
 - Parts prices to be subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company
 - Approved by Repairer

Admin LG 02 by
p/p 11/05/23
total: 810.56 (P/P)