



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref:	CS3/SMO23004042/Kvy3m4-1
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Date:	11/05/2023
			Code:	SMO
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SMV 2939J	<b>Veh. Inspected</b>	SKS 6709U
	<b>Policy No.</b>	D22MTPV01020860	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	CMTD2301536/GPL	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	GNOH PAU LOONG	<b>Assign Date</b>	08/05/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	BMW 316I (A)	<b>c.c</b>	1598
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
	<b>Chassis No.</b>	WBA3A160X0NS38395	<b>Colour</b>	WHITE
	<b>Odometer</b>	176173 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	245/35 ZR19	MICHELIN	7 mm
	<b>L/H Front Tyre</b>	245/35 ZR19	MICHELIN	7 mm
	<b>R/H Rear Tyre</b>	245/35 ZR19	MICHELIN	7 mm
	<b>L/H Rear Tyre</b>	245/35 ZR19	MICHELIN	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	15/04/2023	<b>Inspection Date</b>	20/04/2023
	<b>Survey held at</b>	SOON LEE CHOON AUTO SERVICES BLK 5032 ANG MO KIO IND.PARK 2 #01-283 . SINGAPORE 569535		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>