



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | | | |
|--|--|---|----------------------------------|
| Affiliated to Federation Internationale Des Experts En Automobile | | CS3/SMO23004042/Kvy3-1 | |
| SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 | | Ref: CS3/SMO23004042/Kvy3 Date: 19/04/2023 08/05/2023 Code: SMO | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | |
| Insured Veh. | SMV 2939J | Veh. Inspected | SKS 6709U |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | CMTD2301536/GPL | Excess (\$) | 0.00 |
| Assign From | IRENE HENRY | Assign Date | 19/04/2023 08/05/2023 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 15/04/2023 | Inspection Date | 20/04/2023 |
| Survey held at | SOON LEE CHOON AUTO SERVICES BLK 5032 ANG MO KIO IND.PARK 2 #01-283 . SINGAPORE 569535 | | |
| 5a. Remarks | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | |