

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 201605878Z)
60 JALAN LAM HUAT, CARROS CENTRE
#05-68 (S737869)

TO	: AIG	DATE	: 13-Feb-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
<u>VEHICLE DETAILS</u>			
		VEHICLE NO	: GBJ2112X
		MODEL	: TOYOTA HIACE
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE	1	\$ 1,896.00	\$ 1,896.00
2	TAILGATE INNER LOCK	1	\$ 257.60	\$ 257.60
3	TAILGATE EMBLEM 'HIACE'	1	\$ 35.20	\$ 35.20
4	REAR BUMPER	1	\$ 598.00	\$ 598.00
5	REAR END PANEL (INNER)	1	\$ 547.10	\$ 547.10
6	REAR END PANEL (OUTER)	1	\$ 850.20	\$ 850.20
7	REAR END PANEL EXTEND PANEL	2	\$ 398.70	\$ 797.40

TOTAL PRICE	\$ 4,981.50
LESS 25%	\$ 1,245.38
SUB TOTAL PRICE	\$ 3,736.13

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP	8	\$ 6.50	\$ 52.00
2	TAILGATE STICKER '70km/h'	1	\$ 20.00	\$ 20.00
3	TAILGATE COMPANY STICKER	1	\$ 100.00	\$ 100.00

TOTAL	\$ 172.00
--------------	------------------

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING AND REPLACE PARTS	\$600.00		
2	SPRAY PAINTING TO AFFECTED AREA	\$600.00		
3	TUFF COAT	\$100.00		
4	WIRNING, BULB CHECKING	\$80.00		

TOTAL \$1,380.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,908.13
TOTAL LABOUR COST : \$ 1,380.00
TOTAL REPAIR COST : \$ 5,288.13