

ASS. REC. BY:

REF:

A15/23004669/Kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____ My Car

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$156K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 01 days Res.: Yes or No

Lum Sum: 1.13.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNO 3987X Yr Regn: 12, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy ~~Peris~~ Altir.c.c 178P

Colour: Mr. White A/C: Insured / Std / NI / NA

Sp. Reading: 13922P T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR 2B83B E.5 00008676

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FR18P

Front: P Rear: d

R/Bal: mm R/Bal: mm

L/Bal: mm L/Bal: mm

D.O.A. 30/4/23 D.O.I. 5/5/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt o/s door mirror

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/5 \$638.75 Cash

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee:

Transportation

S + RS. SI

Fines

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)



MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 S737896

HP: 98888885

Estimation

Date: 5/5/2023

Vehicle: SND3987X

Make / Model: TOYOTA ALTIS

INS: ALLIANZ

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	SIDE MIRROR <i>my loose</i>	1	\$ 685.00	\$ 685.00 <i>✓</i>
	TOTAL PART			\$ 685.00
	LIST DOWN	25%		\$ 171.25
	AFTER LIST DOWN			\$ 513.75
	SPEICAL NETT			
1	FRONT SIDE MIRROR CLIPS	1	\$ 50.00	\$ <i>✓</i> 50.00 <i>X</i>
	TOTAL AMOUNT			\$ 50.00
	LABOUR			
1	CHECK WIRING	1	\$ 50.00	\$ 50.00 <i>15% ✓</i>
2	R+R FRONT SIDE MIRROR	1	\$ 100.00	\$ 100.00 <i>✓</i>
3	KNOCK	1	\$ 200.00	\$ 200.00 <i>X</i>
4	SPRAY	1	\$ 200.00	\$ 200.00 <i>601</i>
	TOTAL AMOUNT			\$ 300.00
	Parts Replacement Amount			\$ 563.75
	Total Amount for Labour			\$ 300.00
	Total Amount			\$ 863.75

Not Notified

1 day

\$ 863.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: