



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 S737896

HP: 98888885

Estimation

Date: 5/5/2023

Vehicle: SND3987X

Make / Model: TOYOTA ALTIS

INS: ALLIANZ

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	SIDE MIRROR <i>my loose</i>	1	\$ 685.00	\$ 685.00
	TOTAL PART			\$ 685.00
	LIST DOWN	25%		\$ 171.25
	AFTER LIST DOWN			\$ 513.75
	SPEICAL NETT			
1	FRONT SIDE MIRROR CLIPS	1	\$ 50.00	\$ 50.00
	TOTAL AMOUNT			\$ 50.00
	LABOUR			
1	CHECK WIRING	1	\$ 50.00	\$ 50.00
2	R+R FRONT SIDE MIRROR	1	\$ 100.00	\$ 50.00
3	KNOCK	1	\$ 200.00	\$ 100.00
4	SPRAY	1	\$ 200.00	\$ 100.00
	TOTAL AMOUNT			\$ 300.00
	Parts Replacement Amount			\$ 563.75
	Total Amount for Labour			\$ 300.00
	Total Amount			\$ 863.75

Not As shown

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: