

ORIMAGE ENTERPRISES PTE. LTD.
5 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0121/2023
DATE : 06-MAY-2023

ALLIANZ INSURANCE SINGAPORE PTE LTD
9 ROBINSON ROAD
#09-01 SINGAPORE
S(068897)
TEL : 6395 8973
FAX :

OWNER'S NAME : WEE CHONG CHEUT (XU CHONGJUE)
ADDRESS : APT BLK 88 DAWSON ROAD
#23-37
S(142088)
TELEPHONE NO : 91055364

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800092809-04 AIG
VEHICLE NO : SMD1078U
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YE29096
CHASSIS NO : JF1SJ5KC5JG111547
MILEAGE : 1 KM
DATE IN : 06/05/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 06/05/2023

Print Date : 06/05/2023
Print Time : 13:49:50

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMD1078U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TOWACC	VEHICLE TOWED TO MOTOR IMAGE DUE TO ACCIDENT	180.00	inwork?
2	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST ALLIANZ INS-SMR3846H		
3	ZZ/001	DOA:30/APR/2023 TIME:1057 HRS LOCATION:TELOK BLANGAH		
4	ZZ/002	REPLACE REAR BUMPER, BUMPER BEAM, END PANEL, SPARE TYRE FLOOR & TAILGATE / @ 600 x 52	3500.00	3000
5	ZZ/003	RESPRAY REAR BUMPER, BUMPER BEAM, END PANEL, SPARE TYRE FLOOR & TAILGATE / @ 520 x 4	3000.00	2080
6	ZZ/004	TRANSFER TAILGATE MECHANISM	150.00	
7	ZZ/005	INSTALL REAR WINDSCREEN	300.00	
8	ZZ/006	TO SUPPLY & INSTALL REAR WINDSCREEN SOLAR FILM	145.00	
9	ZZ/007	INSTALL REAR CARGO STEP PANEL	100.00	60
10	ZZ/008	TRANSFER REVERSE SENSOR (OLD TO NEW BUMPER)	100.00	80
11	ZZ/009	REMOVE & REFIX EXHAUST	150.00	?
12	ZZ/011	FAULT DIAGNOSTIC (RESET)	280.00	
13	ZZ/012	SUNDRIES	100.00	20
14	ZZ/10	TO CONDUCT REAR ANTI-RUST COATING	580.00	?
TOTAL LABOUR CHARGES			8585.00	

LIST FOR ACCIDENT VEHICLE REGN NO SMD1078U

S/NO PARTS DESCRIPTION

DAMAGED PARTS & PRICES

	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 MUFFLER ASSY RH NA ?	44300SG010			617.90	
2 FLOOR PAN R R CP <i>repair</i>	52129SG0019P			444.00	
3 SKIRT COMPL REAR END PANEL <i>bt/photo</i>	52401SG0109P			296.00	
4 BUMPER FACE REAR FORESTER IL <i>de/</i>	57704SG012			610.50	
5 BRKT SD R RH <i>ne/</i>	57707SG080			14.80	
6 BRKT SD R LH <i>ne/</i>	57707SG090			14.80	
7 BEAM COMPL R EU <i>bt/</i>	57711SG0219P			296.00	
8 COVER HOOK R <i>X</i>	57731SG010NN			13.00	
9 COVER BMPR R (EXHAUST) <i>X</i>	57731SG060			14.80	
10 PANEL CPL R/G NA <i>bt/</i>	60809SG0109P			1102.60	
11 GLASS R/G <i>ne/photo</i>	63019SG000			821.40	
12 RUBBER DAM GLS <i>ne/</i>	63232SG000			7.40	
13 RUBBER R/G <i>ne/</i>	63232SG010			13.00	
14 CLIP BMPR *9PCS <i>ne/</i>	909140007			21.60	
15 CLIP *2PCS <i>ne/</i>	909140062			6.00	
16 LETTER MARK FORESTOR R <i>ne/</i>	93079SG000			40.70	
17 LETTER MK R SUB <i>ne/</i>	93079SG030			66.60	
18 CARGO STEP PANEL (RESIN) FORESTER <i>de/</i>	E775ESG000			420.00	

SUB TOTAL

LESS DISCOUNT ()

GRAND TOTAL

OVERALL TOTAL

0.00 0.00 4821.10 0.00

0.00 0.00 0.00 0.00

0.00 0.00 4821.10 0.00

4821.10

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

ESTIMATE FOR VEHICLE REGN NO SMD1078U

LABOUR CHARGES	8585.00
SPARE PARTS CHARGES	4821.10
AND TOTAL	13406.10 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - 4p 90011068
SURVEYED DATE	:	10/05/23 @ 11 20
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 8 days
LIABILITY	:	0.00
REMARKS	:	Resy before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: