

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0121/2023
DATE : 06-MAY-2023

ALLIANZ INSURANCE SINGAPORE PTE LTD
9 ROBINSON ROAD
#09-01 SINGAPORE
S(068897)
TEL : 6395 8973
FAX :

OWNER'S NAME : WEE CHONG CHEUT (XU CHONGJUE)
ADDRESS : APT BLK 88 DAWSON ROAD
#23-37
S(142088)
TELEPHONE NO : 91055364

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800092809-04 AIG
VEHICLE NO : SMD1078U
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YE29096
CHASSIS NO : JF1SJ5KC5JG111547
MILEAGE : 1 KM
DATE IN : 06/05/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 06/05/2023

Print Date : 06/05/2023
Print Time : 13:49:50

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMD1078U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TOWACC	VEHICLE TOWED TO MOTOR IMAGE DUE TO ACCIDENT	180.00	
2	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST ALLIANZ INS-SMR3846H		
3	ZZ/001	DOA:30/APR/2023 TIME:1057 HRS LOCATION:TELOK BLANGAH		
4	ZZ/002	REPLACE REAR BUMPER,BUMPER BEAM,END PANEL,SPARE TYRE FLOOR & TAILGATE	3500.00	
5	ZZ/003	RESPRAY REAR BUMPER,BUMPER BEAM,END PANEL,SPARE TYRE FLOOR & TAILGATE	3000.00	
6	ZZ/004	TRANSFER TAILGATE MECHANISM	150.00	
7	ZZ/005	INSTALL REAR WINDSCREEN	300.00	
8	ZZ/006	TO SUPPLY & INSTALL REAR WINDSCREEN SOLAR FILM	145.00	
9	ZZ/007	INSTALL REAR CARGO STEP PANEL	100.00	
10	ZZ/008	TRANSFER REVERSE SENSOR (OLD TO NEW BUMPER)	100.00	
11	ZZ/009	REMOVE & REFIX EXHAUST	150.00	
12	ZZ/011	FAULT DIAGNOSTIC (RESET)	280.00	
13	ZZ/012	SUNDRIES	100.00	
14	ZZ/10	TO CONDUCT REAR ANTI-RUST COATING	580.00	
		TOTAL LABOUR CHARGES	8585.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMD1078U

		DAMAGED PARTS & PRICES			S/LIST REMARKS
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	
1	MUFFLER ASSY RH NA	44300SG010			617.90
2	FLOOR PAN R R CP	52129SG0019P			444.00
3	SKIRT COMPL REAR END PANEL	52401SG0109P			296.00
4	BUMPER FACE REAR FORESTER IL	57704SG012			610.50
5	BRKT SD R RH	57707SG080			14.80
6	BRKT SD R LH	57707SG090			14.80
7	BEAM COMPL R EU	57711SG0219P			296.00
8	COVER HOOK R	57731SG010NN			13.00
9	COVER BMPR R (EXHAUST)	57731SG060			14.80
10	PANEL CPL R/G NA	60809SG0109P			1102.60
11	GLASS R/G	63019SG000			821.40
12	RUBBER DAM GLS	63232SG000			7.40
13	RUBBER R/G	63232SG010			13.00
14	CLIP BMPR *9PCS	909140007			21.60
15	CLIP *2PCS	909140062			6.00
16	LETTER MARK FORESTOR R	93079SG000			40.70
17	LETTER MK R SUB	93079SG030			66.60
18	CARGO STEP PANEL (RESIN)FORESTER	E775ESG000			420.00
SUB TOTAL			0.00	0.00	4821.10
LESS DISCOUNT ()			0.00	0.00	0.00
GRAND TOTAL			0.00	0.00	4821.10
OVERALL TOTAL			4821.10		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMD1078U

TOTAL LABOUR CHARGES 8585.00
TOTAL SPARE PARTS CHARGES 4821.10

GRAND TOTAL 13406.10 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.