

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0121/2023
DATE : 06-MAY-2023

ALLIANZ INSURANCE SINGAPORE PTE LTD
9 ROBINSON ROAD
#09-01 SINGAPORE
S(068897)
TEL : 6395 8973
FAX :

OWNER'S NAME : WEE CHONG CHEUT (XU CHONGJUE)
ADDRESS : APT BLK 88 DAWSON ROAD
#23-37
S(142088)
TELEPHONE NO : 91055364

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800092809-04 AIG
VEHICLE NO : SMD1078U
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YE29096
CHASSIS NO : JF1SJ5KC5JG111547
MILEAGE : 1 KM
DATE IN : 06/05/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 06/05/2023

Print Date : 06/05/2023
Print Time : 13:49:50

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMD1078U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TOWACC	VEHICLE TOWED TO MOTOR IMAGE DUE TO ACCIDENT	180.00	inwork? /
2	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST ALLIANZ INS-SMR3846H		
3	ZZ/001	DOA:30/APR/2023 TIME:1057 HRS LOCATION:TELOK BLANGAH		
4	ZZ/002	REPLACE REAR BUMPER,BUMPER BEAM,END PANEL,SPARE TYRE FLOOR & TAILGATE / @ 600 x 5 2	3500.00	3000 /
5	ZZ/003	RESPRAY REAR BUMPER,BUMPER BEAM,END PANEL,SPARE TYRE FLOOR & TAILGATE / @ 520 x 4	3000.00	2080 /
6	ZZ/004	TRANSFER TAILGATE MECHANISM	150.00	/
7	ZZ/005	INSTALL REAR WINDSCREEN	300.00	/
8	ZZ/006	TO SUPPLY & INSTALL REAR WINDSCREEN SOLAR FILM	145.00	/
9	ZZ/007	INSTALL REAR CARGO STEP PANEL	100.00	60 /
10	ZZ/008	TRANSFER REVERSE SENSOR (OLD TO NEW BUMPER)	100.00	80 /
11	ZZ/009	REMOVE & REFIX EXHAUST	150.00	? /
12	ZZ/011	FAULT DIAGNOSTIC (RESET)	280.00	/
13	ZZ/012	SUNDRIES	100.00	20 /
14	ZZ/10	TO CONDUCT REAR ANTI-RUST COATING	580.00	? X 11
TOTAL LABOUR CHARGES			8585.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMD1078U

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	MUFFLER ASSY RH NA <i>9. X nn</i>	44300SG010			617.90	
2	FLOOR PAN R R CP <i>repair</i>	52129SG0019P			444.00	
3	SKIRT COMPL REAR END PANEL <i>bt/photo</i>	52401SG0109P			296.00	✓
4	BUMPER FACE REAR FORESTER IL <i>de</i>	57704SG012			610.50	✓
5	BRKT SD R RH <i>ne</i>	57707SG080			14.80	✓
6	BRKT SD R LH <i>ne</i>	57707SG090			14.80	✓
7	BEAM COMPL R EU <i>bt</i>	57711SG0219P			296.00	✓
8	COVER HOOK R <i>X nn</i>	57731SG010NN			13.00	
9	COVER BMPR R (EXHAUST) <i>X nn</i>	57731SG060			14.80	
10	PANEL CPL R/G NA <i>bt</i>	60809SG0109P			1102.60	✓
11	GLASS R/G <i>ne/photo</i>	63019SG000			821.40	✓
12	RUBBER DAM GLS <i>ne</i>	63232SG000			7.40	✓
13	RUBBER R/G <i>ne</i>	63232SG010			13.00	✓
14	CLIP BMPR *9PCS <i>ne</i>	909140007			21.60	✓
15	CLIP *2PCS <i>ne</i>	909140062			6.00	✓
16	LETTER MARK FORESTOR R <i>ne</i>	93079SG000			40.70	✓
17	LETTER MK R SUB <i>ne</i>	93079SG030			66.60	✓
18	CARGO STEP PANEL (RESIN)FORESTER <i>de</i>	E775ESG000			420.00	✓
SUB TOTAL			0.00	0.00	4821.10	0.00
LESS DISCOUNT ()			0.00	0.00	0.00	0.00
GRAND TOTAL			0.00	0.00	4821.10	0.00
OVERALL TOTAL			4821.10			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMD1078U

TOTAL LABOUR CHARGES	8585.00
TOTAL SPARE PARTS CHARGES	4821.10
GRAND TOTAL	13406.10 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - 4p 90010068
SURVEYED DATE	:	10/05/23 @ 1120
AUTHORIZED DATE	:	8 days + 1 = 9 days
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	Resy before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0121/2023
DATE : 06-MAY-2023

ALLIANZ INSURANCE SINGAPORE PTE LTD
9 ROBINSON ROAD
#09-01 SINGAPORE
S(068897)
TEL : 6395 8973
FAX :

OWNER'S NAME : WEE CHONG CHEUT (XU CHONGJUE)
ADDRESS : BLK 23 HILLVIEW AVENUE
#04-12
S(669557)
TELEPHONE NO : 91055364

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800092809-04 AIG
VEHICLE NO : SMD1078U
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YE29096
CHASSIS NO : JF1SJ5KC5JG111547
MILEAGE : 1 KM
DATE IN : 06/05/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 06/05/2023

Print Date : 16/06/2023
Print Time : 14:52:37

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMD1078U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TOWACC	VEHICLE TOWED TO MOTOR IMAGE DUE TO ACCIDENT	180.00	180.00
2	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST ALLIANZ INS-SMR3846H		
3	ZZ/001	DOA:30/APR/2023 TIME:1057 HRS LOCATION:TELOK BLANGAH		
4	ZZ/002	REPLACE REAR BUMPER,BUMPER BEAM,END PANEL,SPARE TYRE FLOOR & TAILGATE	3500.00	3000.00
5	ZZ/003	RESPRAY REAR BUMPER,BUMPER BEAM,END PANEL,SPARE TYRE FLOOR & TAILGATE	3000.00	2080.00
6	ZZ/004	TRANSFER TAILGATE MECHANISM	150.00	150.00
7	ZZ/005	INSTALL REAR WINDSCREEN	300.00	300.00
8	ZZ/006	TO SUPPLY & INSTALL REAR WINDSCREEN SOLAR FILM	145.00	145.00
9	ZZ/007	INSTALL REAR CARGO STEP PANEL	100.00	60.00
10	ZZ/008	TRANSFER REVERSE SENSOR (OLD TO NEW BUMPER)	100.00	80.00
11	ZZ/009	REMOVE & REFIX EXHAUST	150.00	150.00
12	ZZ/011	FAULT DIAGNOSTIC (RESET)	280.00	280.00
13	ZZ/012	SUNDRIES	100.00	20.00
14	ZZ/013	REPLACE FRONT BUMPER & ENERGY ABSORBER (1.0 SUPP) <i>Wale</i>	600.00	600.00
15	ZZ/014	RESPRAY FRONT BUMPER (1.0) <i>suppl</i>	520.00	520.00
16	ZZ/10	TO CONDUCT REAR ANTI-RUST COATING	580.00	.00
TOTAL LABOUR CHARGES			9705.00	7565.00

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMD1078U

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				REMARKS
			NETT	LIST	S/NETT	S/LIST	
1	MUFFLER ASSY RH NA	44300SG010			617.90		X
2	FLOOR PAN R R CP	52129SG0019P			444.00		X
3	SKIRT COMPL REAR END PANEL	52401SG0109P			296.00		OK
4	BUMPER FACE REAR FORESTER IL	57704SG012			610.50		OK
5	BRKT SD R RH	57707SG080			14.80		OK
6	BRKT SD R LH	57707SG090			14.80		OK
7	BUMPER FACE F NA (FOR H/L WSH) <i>Suppl der</i>	57709SG030			610.50		OK
8	BEAM COMPL R EU	57711SG0219P			296.00		OK
9	ENERGY ABSOR F <i>bt/cupl</i>	57722SG020			129.50		OK
10	COVER HOOK R	57731SG010NN			13.00		X
11	COVER BMPR R (EXHAUST)	57731SG060			14.80		X
12	PANEL CPL R/G NA	60809SG0109P			1102.60		OK
13	GLASS R/G	63019SG000			821.40		OK
14	RUBBER DAM GLS	63232SG000			7.40		OK
15	RUBBER R/G	63232SG010			13.00		OK
16	CLIP BMPR *9PCS	909140007			21.60		OK
17	CLIP *2PCS	909140062			6.00		OK
18	LETTER MARK FORESTOR R	93079SG000			40.70		OK
19	LETTER MK R SUB	93079SG030			66.60		OK
20	CARGO STEP PANEL (RESIN)FORESTER	E775ESG000			420.00		OK
21	FRONT NUMBER PLATE <i>bt/cupl</i>	WM001			45.00		OK
SUB TOTAL			0.00	0.00	4516.40		0.00
LESS DISCOUNT ()			0.00	0.00	0.00		0.00
GRAND TOTAL			0.00	0.00	4516.40		0.00
OVERALL TOTAL			4516.40				

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMD1078U

		DAMAGED PARTS & PRICES					
S/NO	PARTS DESCRIPTION	PARTS NUMBER					
			NETT	LIST	S/NETT	S/LIST	REMARKS

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SMD107BU

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	4516.40
---------------------	---------

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	7565.00
TOTAL SPARE PARTS CHARGES	4516.40

TOTAL CHARGES	12081.40
ADD 8 % GST	966.51

GRAND TOTAL	13047.91
-------------	----------

TOW JOB WORK ORDER

GST Reg No. : 19-9806389-N

Co. Reg No. : 199806389N



AUTOSWIFT RECOVERY PTE LTD

Contract :

Subaru Motor Image

W/Order No. : T 201107

PART A: JOB DETAILS

Service Date 30.4.2023 Time Received 1145

Member / Customer's Name Miss Lee Time Arrived 1221

Membership / NRIC No. J Time Completed _____

Contact No. 84 91055364 / 94579812 Total Mileage _____

Vehicle Registration No. SMD 10784 Car Make / Model Subaru Forester

Breakdown Location 766k Blayck Towed Destination Leng Lee

NORMAL TOWING	ADDITIONAL SERVICES
☐ Straight Towing	☐ Multi-Storey / Basement Car Park
☒ Straight Towing with King Dolley	☐ Woodlands Checkpoint / Tuas 2nd Link
☐ Flat Bed / Car Carrier	☐ Sentosa / Jurong Island
☒ Flat Bed / Car Carrier with King Dolley	☒ Accident Towing
☐ Heavy Goods Vehicle / Light Goods Vehicle	☐ Car Ditched / Winched Up / Crane Up
☐	☐ Dismantle Shaft / Release Brakes
☐	☐

SURCHARGES / OTHERS	ROADSIDE SERVICES
☒ Sunday / Public Holiday Towing (full day)	☐ Jump Start
☐ Midnight Towing (2400hrs to 0700hrs)	☐ Tyre Replacement
☐ Call Cancelled / Car Missing	☐ Patch Tyre Service
☐ Standby / Waiting Time _____	☐ Repair Tyre & Returned
☐ Luxury Cars	☐ Battery Replacement
☐ AA Membership Enrolment / AA Renewal	Battery Receipt No: _____

REMARKS / COMMENTS BY TOW CREW

76 YN 2075 B h

Tow Crew ID Truck No. Tow Crew's Signature

PART B: MEMBER / CUSTOMER ACKNOWLEDGEMENT

- I authorise AutoSwift Recovery Pte Ltd to tow my vehicle to the above-mentioned workshop of my choice.
- I have been advised to remove all valuables (handphone, laptop, parking coupons, cash cards etc) from the vehicle.
- I understand that items left behind are at my own risk and that AutoSwift Recovery Pte Ltd will not be held responsible for any losses.
- I accept that there may be damages to my vehicle arising from the towing operation and I will not hold AutoSwift Recovery liable for the damages.

5 Remarks : h

Member / Customer Signature 30.4.23 Date

PART C: WORKSHOP / AGENT DECLARATION

- I hereby represent the company receiving the above mentioned vehicle.
- AutoSwift Recovery Pte Ltd will not be held responsible for any damages or loss of valuables discovered while the vehicle is in our possession.

3 Remarks : h

Workshop's Representative Signature 30/04/2023 Date

Workshop's Stamp

WORKSHOP COPY

Swift and Safe

AutoSwift Recovery Pte Ltd

(A wholly-owned subsidiary of AA Singapore)

Head Office: 2 Kung Chong Road #06-01 AA Centre Singapore Tel: 6333 8811 Fax: 6733 5094