

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Reg. No: 201427944N

ATTENTION:	MOTOR CLAIMS DEPARTMENT	GK81202761
DATE:	08-05-23	
CLAIM TYPE:	T/P CLAIM	
TO:	INDIA	
VEHICLE DETAILS		
VEHICLE NO:	SMG563B	Xiao Teng
MAKE & MODEL:	HONDA SHUTTLE 1.5	
CHASSIS NO:		
ACCIDENT DETAILS		
DATE:	6 May, 2023	
TIME:	2235HRS	
THIRD PARTY REQUESTOR:	JACK LI	

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Distorted</i>	1	\$ 1,455.80	\$ <u>1,455.80</u>
2	TAIL GATE LOGO <i>new</i>	1	\$ 55.60	\$ 55.60
3	TAIL GATE EMBLEM <i>new</i>	1	\$ 80.00	\$ 80.00
5	TAIL GATE HINGE <i>new</i>	2	\$ 60.00	\$ 120.00
5	TAIL GATE DAMPER <i>new</i>	2	\$ 190.00	\$ 380.00
6	TAIL GATE LOCK <i>Distorted</i>	1	\$ 210.00	\$ 210.00
6	TAIL GATE INNER BOARD <i>cracked</i>	1	\$ 522.30	\$ 522.30
6	TAIL GATE INNER HANDLE <i>cracked</i>	1	\$ 90.00	\$ 90.00
6	TAIL GATE INNER STOPPER <i>new</i>	2	\$ 20.00	\$ 40.00
7	TAIL GATE WEATHERSTRIP <i>lit</i>	1	\$ 235.90	\$ 235.90
8	TAIL GATE LAMP <i>cracked</i>	2	\$ 480.50	\$ 961.00
9	TAIL GATE BUZZEL <i>Not new</i>	1	\$ 88.20	\$ 88.20
9	TAIL GATE DETECTOR <i>cracked</i>	1	\$ 144.60	\$ 144.60
10	TAIL GATE WINDSCREEN <i>Shattered</i>	1	\$ 1,355.90	\$ <u>1,355.90</u>
10	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 190.00	\$ 190.00
10	TAIL GATE WIPER BLADE ARM <i>new</i>	1	\$ 133.60	\$ 133.60
10	TAIL GATE WIPER BLADE MOTOR <i>Distorted</i>	1	\$ 522.40	\$ 522.40
11	NUMBER PLATE GARNISH <i>cracked</i>	1	\$ 422.50	\$ 422.50
11	NUMBER PLATE LAMP (SET) <i>new</i>	1	\$ 122.00	\$ 122.00
12	REAR BUMPER <i>Distorted</i>	1	\$ 1,355.20	\$ <u>1,355.20</u>
13	REAR BUMPER SIDE RETAINER <i>Distorted</i>	2	\$ 62.40	\$ <u>124.80</u>

17	REAR BUMPER TOWING COVER <i>Distorted</i>	1	\$ 80.00	\$ 80.00	<i>55</i>
16	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 90.00	\$ 180.00	<i>+</i>
17	REAR BUMPER REFLECTOR HOUSING <i>could</i>	2	\$ 115.40	\$ 230.80	<i>✓</i>
16	REAR BUMPER REFLECTOR HOUSING SPONGE <i>could</i>	2	\$ 90.00	\$ 180.00	<i>✓</i>
19	REAR FENDER INNER TRIM BOARD <i>could</i>	2	\$ 680.50	\$ 1,361.00	<i>780</i>
19	TAILLAMP <i>lit</i>	2	\$ 580.00	\$ 1,160.00	<i>✓</i>
19	TAILLAMP PANEL <i>2 yr</i>	2	\$ 320.00	\$ 640.00	<i>+</i>
20	REAR END PANEL (OUTER) <i>Distorted</i>	1	\$ 655.80	\$ 655.80	<i>✓</i>
22	REAR END PANEL TOP GARNISH <i>could</i>	1	\$ 190.00	\$ 190.00	<i>✓</i>
23	REAR FLOOR PANEL <i>Buckled</i>	1	\$ 1,155.80	\$ 1,155.80	<i>✓</i>
23	REAR FLOOR PANEL TOP BOARD <i>Del'd</i>	1	\$ 480.00	\$ 480.00	<i>✓</i>
24	SPARE TYRE TOOL BOX CARRIER <i>Del'd</i>	1	\$ 360.00	\$ 360.00	<i>✓</i>
25	SPARE TYRE TOOL BOX CARRIER BELOW <i>not could</i>	1	\$ 180.00	\$ 180.00	<i>+</i>
19	SPARE TYRE TOOL BOX CARRIER SIDE <i>Del'd</i>	1	\$ 180.00	\$ 180.00	<i>✓</i>
19	EXHAUST PIPE <i>2 pp</i>	1	\$ 955.30	\$ 955.30	<i>+</i>
20	EXHAUST PIPE MOUNTING <i>me</i>	2	\$ 60.00	\$ 120.00	<i>+</i>
21	EXHAUST PIPE HEAT SHEILD	1	\$ 255.40	\$ 255.40	<i>+</i>

TOTAL PRICE \$ 16,973.90

LESS 20% \$ 4,243.48

SUB TOTAL PRICE \$ 12,730.43

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE <i>2nd</i>	1	\$ 50.00	\$ 50.00
3	TAILGATE INNER TRIM CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00
2	TAILGATE WINDSCREEN SEALANT <i>me</i>	1	\$ 120.00	\$ 120.00
2	TAILGATE WINDSCREEN SOLAR FILM <i>me</i>	1	\$ 350.00	\$ 350.00
4	REAR BUMPER CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00
5	REAR FENDER INNER TRIM CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00
6	REAR END PANEL TOP GARNISH CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
8	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 180.00	\$ 180.00
9	REVERSE SENSOR <i>2nd</i>	1	\$ 220.00	\$ 220.00
9	REVERSE CAMERA <i>2nd</i>	1	\$ 450.00	\$ 450.00
9	IN CAR CAMERA <i>Missing</i>	1	\$ 550.00	\$ 550.00

TOTAL \$ 2,150.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 2,200.00	1,200.
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 2,000.00	800.
3	TUFF COAT	1	\$ 200.00	80.

4	WIRING CHECK	1	\$ 120.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	80
6	TRANSFER TAILGATE MECHANISM	1	\$ 180.00	60
7	REMOVE AND REFIX TAILGATE WINDSCREEN	1	\$ 150.00	120
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	50
9	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	1	\$ 100.00	50
10	REMOVE AND REFIX EXHAUST PIPE	1	\$ 220.00	X

2470

TOTAL \$ 5,550.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	14,880.43
TOTAL LABOUR COST	\$	5,550.00
TOTAL REPAIR COST	\$	20,430.43

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

Admin Lj
L/s 08/05/23.

09 Days.

total: 14047.76

L/s: 11.2K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: