

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III23004691/KPA3Q2**Date:** 28/07/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D23MFL0002582
Claimant Vehicle No :	SKT7073H	Insured Vehicle No :	SLK3165M
Date of Loss:	16/04/2023	Nature of Claim:	TP
		Claim No:	MFL2023D0004078

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT7073H		
Make & Model:	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)	Engine No:	K24W71010764
Reg. Date:	19/06/2015 (Man. Year: 2015)	Chassis No:	JHMRC1890FC201799
Colour:	Metallic Grey	Odometer:	109672 km
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		4,964.95		
(S\$)	0.00	4,964.95	-4,964.95	
+ GST 8.00/8.00% (S\$)	0.00	397.20	-397.20	
Nett Amount (S\$)	0.00	5,362.15	-5,362.15	
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		5,662.15		

INSPECTION

Date of Assignment:	03/05/2023		
Date Inspected:	23/05/2023	Inspected At:	Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903 Singapore 729903
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT7073H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >