



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INCOME INSURANCE LIMITED
75 BRAS BASAH ROAD
SINGAPORE 189557
Registration No : SKT7073H
Chassis No : JHMRC1890FC201799
Model : ODYSSEY 2.4 EXV-S 15YM NAVI-RES
Owner's Name : LEE HOCK KIN
Ins Policy No. :
Date of Accident : 18/4/2023

Document No. : SQT23001190 Page 1
Date : 19. Apr 2023
Customer No. : WZN008
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : K24W71010764
Date | Time : 19. Apr 2023 11:34:37 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LEE HOCK HIN OWNER INSURER: TOKIO MARINE ACC DATE: 16/04/2023 SURVEYED BY: DATE: REF NO: TP INSURER: INCOME TP VEH: SLK3165M						
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.60	48.60
04711-T6A-900ZZ	FACE,FR BUMPER	1	749.30	25	561.97	44.96	606.93
71193-T6A-003	SPACERR.FR.BUMPER SIDE	1	12.60	25	9.45	0.76	10.21
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	12.60	25	9.45	0.76	10.21
71112-T6A-921ZA	SPOILER ASSYR.FR.SIDE	1	104.10	25	78.07	6.25	84.32
71117-T6A-921ZA	SPOILER ASSY,L.FR.SIDE	1	104.10	25	78.07	6.25	84.32
71105-T6A-901	GRILLEFR.BUMPER LOWER	1	71.90	25	53.92	4.31	58.23
71108-T6A-P00	LOWER PLATEFR.BUMPER	1	157.40	25	118.05	9.44	127.49
71151-T6A-911	BASE,MID GRILLE	1	205.60	25	154.20	12.34	166.54
71152-T6A-921	UPPER MOLDING,MID GRILLE	1	169.30	25	126.97	10.16	137.13
71153-T6A-921	MID MOLDING,MID GRILLE	1	162.20	25	121.65	9.73	131.38
71154-T6A-921	LOWER MOLDING,R.MID GRILLE	1	43.50	25	32.62	2.61	35.23
71159-T6A-921	LOWER MOLDING,L.MID GRILLE	1	43.50	25	32.62	2.61	35.23
71121-T6A-003	BASEFR.GRILLE	1	180.80	25	135.60	10.85	146.45
71122-T6A-003	MOLDING,FR.GRILLE	1	290.20	25	217.65	17.41	235.06
75700-TA0-A00	EMBLEMFR.	1	30.80	25	23.10	1.85	24.95
90301-ST0-003	NUT,PUSH 3MM	2	2.10	25	3.15	0.25	3.40
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED	1	2516.00	25	1887.00	150.96	2037.96
33150-T6A-Q11	HEADLIGHT ASSY,L.WITH LED	1	2516.00	25	1887.00	150.96	2037.96

Printed on 25/4/2023 7:34:52 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INCOME INSURANCE LIMITED
75 BRAS BASAH ROAD
SINGAPORE 189557
Registration No : SKT7073H
Chassis No : JHMRC1890FC201799
Model : ODYSSEY2.4 EXV-S 15YM NAVI-RES
Owner's Name : LEE HOCK KIN
Ins Policy No. :
Date of Accident : 18/4/2023

Document No. : SQT23001190
Date : 19. Apr 2023
Customer No. : WZN008
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : K24W71010764
Date | Time : 19. Apr 2023 11:34:37 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
60400-T6A-320ZZ	BULKHEAD COMP.FR.	1	465.10	25 X NN	348.82	27.91	376.73
Sum Item					5924.36	473.97	6,398.33
BOSUN	SUNDRIES	1	100.00		100.00	8.00	108.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	160.00	✓ 144.00	160.00	12.80	172.80
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1500.00	50% 585.00	1500.00	120.00	1620.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1500.00	50% 468.00	1500.00	120.00	1620.00
Sum Labor					3260.00	260.80	3,520.80

Survey By

Date & Time

Excess

Status

Signature

Total Amount 9,184.36 734.77 9,919.13

Total (Inclusive of GST) 9,919.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 25/4/2023 7:34:52 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0076868 / INCOME
Chassis No: JHMRC1890FC201799
License No: SKT7073H
Mileage: 109672
Engine No: K24W71010764

Document No: SVO23020434
Printed By: ANIKKALAI
Order Date: 23. May 2023
Order Time: 2:26:08 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	8% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO:)							
	OWNER: LEE HOCK HIN							
	OWNER INSURER: TOKIO MARINE							
	ACC DATE: 16/04/2023							
	SURVEYED BY: KENNETH / LKK							
	DATE: 23/05/2023							
	REF NO:							
	TP INSURER: INCOME							
	TP VEH: SLK3165M							
	SUPPLEMENTARY PART							
71130-T6A-310ZZ	BEAM COMP,FR.BUMPER	B1 1	312.40	25	234.30	18.74	253.04	11
71190-T6A-003	BEAML.FR.BUMPER UPPER	11.1 1	37.30	25	27.97	2.24	30.21	11
91578-T0A-003	CLIPFR.GRILLE	12 4	2.40	25	7.20	0.58	7.78	11