

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 23 May 2023

Preliminary Advice

Vehicle No	: SKR7847C	Accident Date	: 07/05/2023
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MPC23A00067600
Assignment Date	: 09/05/2023	Excess	: S\$1,100.00
Date of Inspection	: 09/05/2023	Est. Duration of Repair	: 5
Inspection At	: SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,467.60	(Estimate \$5,340.00 + Supplementary \$127.60)
Revised Amount	:S\$	4,137.60	(Inclusive of supplementary)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	4,137.60	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	32,000.00
COE / PARF Rebate	:S\$	18,044.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,956.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.