

Section A - Accident Details

Registration Number	SHF337C
Case Reference Number	TAX/05/23/2022
Registration Date	12/Dec/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	SOH LAI KIM
Type of Accident	Head to Rear
Accident Date and Time	8/May/2023 2:15 AM
Accident Reported Date and Time	8/May/2023 3:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118367
Special Instruction to ARC, if any	TP / REAR PORTION
Prepared Date and Time	8/May/2023 4:12 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,690.00	\$400.00
Total Spray Cost	\$2,234.00	\$550.00
Total Spare Part Cost	\$11,972.65	\$2,983.30
Total Other Cost	\$1,435.00	(\$533.30)
TOTAL COST	\$17,331.65	\$3,400.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	9.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / INCOME
ARC / Surveyor Sign Off Date	15/05/2023 7:50 AM	13/05/2023 10:32 AM
Signature		
Remarks	INITIAL = 9 DAYS WITH SUPPLEMENTARY = 0 DAYS TOTAL = 9 DAYS	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Taufikh (LKK) / HP : 9749 5749 / Email : taufikh@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2305-0314	Invoice Number	
Quotation Date	26.05.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,690.00	\$400.00
Total Labour	\$1,690.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$220.00	\$0.00
TO RESPRAY BUMPER BEAM	\$220.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$220.00	\$0.00
TO RESPRAY REAR SPOILER	\$220.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00	\$150.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$2,234.00	\$550.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$30.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$475.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$180.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$833.30)
Total Other Costs	\$1,435.00	(\$533.30)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Check	X
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace	Replace	√
		52462-47130	PAD, RR BUMPER, RH & LH , 3	0.00	\$12.00	0.00	\$0.00	Replace	Check	X
		52462-47030	PAD, RR BUMPER, RH & LH , 2	0.00	\$4.30	0.00	\$0.00	Replace	Check	X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
80 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 03/06/2023

User ID : PohSuan

	52462-47020	PAD, RR BUMPER, RH & LH , 1	0.00	\$4.30	0.00	\$0.00	Replace	Check	X
	52461-47070	PAD, RR BUMPER, CTR	0.00	\$12.00	0.00	\$0.00	Replace	Check	X
	52191-47030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$12.30	0.00	\$0.00	Replace	Check	X
	52599-68030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X
	52576-47060	RETAINER, RR BUMPER, LH	1.00	\$143.60	25.00	\$107.70	Replace	Replace	√
	52592-47080	SEAL, RR BUMPER , LH	1.00	\$128.00	25.00	\$96.00	Replace	Replace	√
	52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	√
	52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$405.00	25.00	\$303.75	Replace	Replace	√
	81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1.00	\$42.20	25.00	\$31.65	Replace	Replace	√
	81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$42.20	0.00	\$0.00	Replace	Not Given	X
	9018906029	REAR BUMPER GROMMET SCREW	1.00	\$2.20	25.00	\$1.65	Replace	Replace	√
	58399-47030	COVER, REAR FLOOR UNDER, LH	0.00	\$261.60	0.00	\$0.00	Replace	Check	X
	66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Check	X
	81551-47481	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$367.30	0.00	\$0.00	Replace	Not Given	X
	81561-47471	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$367.30	0.00	\$0.00	Replace	Not Given	X
	81497-47040	COVER, REAR COMBINATION LAMP, RH	0.00	\$75.90	0.00	\$0.00	Replace	Not Given	X
	81498-47040	COVER, REAR COMBINATION LAMP, LH	0.00	\$75.90	0.00	\$0.00	Replace	Not Given	X
	81457-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$282.70	0.00	\$0.00	Replace	Not Given	X
	81456-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$282.70	0.00	\$0.00	Replace	Not Given	X
	81580-47070	LAMP ASSY, REAR, RH	0.00	\$317.80	0.00	\$0.00	Replace	Not Given	X
	81590-47070	LAMP ASSY, REAR, LH	0.00	\$317.80	0.00	\$0.00	Replace	Not Given	X
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
	89997-30100	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given	X
	61602-47180	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$943.10	0.00	\$0.00	Replace	Not Given	X
	65638-47060	LINER, REAR FENDER , LH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given	X
	58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Not Given	X
	58311-47130	SPARE TYRE PANEL , PAN, REAR FLOOR	0.00	\$630.30	0.00	\$0.00	Replace	Not Given	X
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	67005-47530	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$1,238.40	25.00	\$928.80	Replace	Replace	√
	67293-47031	TAIL GATE CUSHION, BACK DOOR LOWER STOPPER	0.00	\$26.50	0.00	\$0.00	Replace	Not Given	X
	67281-47020	TAIL GATE STOPPER, BACK DOOR , RH & LH	0.00	\$34.70	0.00	\$0.00	Replace	Not Given	X
	67281-47020	TAIL GATE STOPPER, BACK DOOR , RH & LH	0.00	\$34.70	0.00	\$0.00	Replace	Not Given	X
	67881-47051	TAIL GATE WEATHERSTRIP, BACK DOOR	0.00	\$402.50	0.00	\$0.00	Replace	Not Given	X
	56117-50140	TAIL GATE DAM, BACK DOOR GLASS UPPER	1.00	\$31.30	25.00	\$23.48	Replace	Replace	√
	68105-47292	TAIL GATE GLASS SUB-ASSY, BACK DOOR	0.00	\$1,795.00	0.00	\$0.00	Replace	Not Given	X
	75571-47011	TAIL GATE MOULDING GLASS, BACK DOOR	1.00	\$38.50	25.00	\$28.88	Replace	Replace	√
	64801-47031	TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	0.00	\$821.20	0.00	\$0.00	Replace	Not Given	X
		SEALANT W/SCREEN (3PCS)	3.00	\$37.00	0.00	\$111.00	Replace	Replace	√
	76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$992.30	25.00	\$744.23	Replace	Replace	√
	68810-47061	TAIL GATE BACK DOOR HINGE ASSY, RH & LH	0.00	\$66.20	0.00	\$0.00	Replace	Not Given	X
	69350-47050	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$505.50	0.00	\$0.00	Replace	Not Given	X
	69321-47010	TAIL GATE LOCK COVER , BACK DOOR	0.00	\$32.70	0.00	\$0.00	Replace	Not Given	X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/06/2023

User ID : PohSuan

		75403-48010	EMBLEM SUB-ASSY REAR	0.00	\$77.40	0.00	\$0.00	Replace	Not Given	X
		75441-47220	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
		75442-47200	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
		76839-47030	COVER, TAIL GATE BACK DOOR GARNISH	0.00	\$9.20	0.00	\$0.00	Replace	Not Given	X
		76085-47916	SPOILER SUB-ASSY, REAR	0.00	\$1,704.20	0.00	\$0.00	Replace	Not Given	X
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	√
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√
Total					\$15,022.80		\$2,925.25			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		75403-48010	EMBLEM SUB-ASSY REAR	1.00	\$77.40	25.00	\$58.05	Replace	Replace	√
Total					77.40		58.05			

	2,983.30	
+	400.00	
+	850.00	L/S \$3,400/-
	4,233.30	
	-20%	
	3,386.64	