

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

Ezlyn

DATE : 02.05.2023

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **YQ6010X**
MODEL : **TOYOTA DYNA**
DATE OF ACCIDENT : 29.04.2023
TIME OF ACCIDENT : 08:45 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,370.00	\$ 1,370.00 ✓
2	TAILGATE HINGE <i>2 pieces Best</i>	4	\$ 165.00	\$ 660.00 330
3	TAILGATE SIDE LOCK <i>RH Dented</i>	2	\$ 125.00	\$ 250.00 125
4	TAILGATE STOPPER RUBBER <i>RH int</i>	2	\$ 35.90	\$ 71.80 35.90
5	TAILGATE STOPPER BRACKET <i>RH Best</i>	2	\$ 175.00	\$ 350.00 175
6	CARGO BED SIDE PANEL RH <i>Repair</i>	1	\$ 1,522.10	\$ 1,522.10 +
7	SIDE GATE <i>RH Dented</i>	2	\$ 1,865.00	\$ 3,730.00 1865
8	SIDE GATE SAFETY LOCK <i>new</i>	2	\$ 132.10	\$ 264.20 +
9	TAIL LAMP <i>RH on Ld</i>	2	\$ 251.80	\$ 503.60 251.80
10	TAIL LAMP SUPPORT BRACKET <i>RH Best</i>	2	\$ 185.00	\$ 370.00 185
11	TAIL LAMP REFLECTOR (ROUND) RH <i>new</i>	1	\$ 65.10	\$ 65.10 +
12	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 69.10	\$ 138.20 +
13	REAR STICKER 'DYNA' <i>new</i>	1	\$ 85.70	\$ 85.70 +
14	REAR END PANEL <i>Dented</i>	1	\$ 1,245.00	\$ 1,245.00 495
15	REAR REINFORCEMENT <i>Dented</i>	1	\$ 1,850.00	\$ 1,850.00 1000(SN)
16	REAR REINFORCEMENT BRACKET <i>Best</i>	2	\$ 486.20	\$ 972.40 600(SN)
17	REAR SPARE TYRE CHAIN BOX <i>new</i>	1	\$ 265.70	\$ 265.70 +

4918.40

3688.80

SN 1600

TOTAL PRICE \$ 13,713.80
LESS 25% \$ 3,428.45
SUB TOTAL PRICE \$ 10,285.35

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **YQ6010X**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 29.04.2023
 TIME OF ACCIDENT : 08:45 HOURS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
2	TAIL GATE '70KM/H' STICKER <i>3/12</i>	1	\$ 40.00	\$ 40.00 <i>15</i>
3	TAIL GATE '12PAX' STICKER	1	\$ 40.00	\$ 40.00 <i>15</i>
4	TAIL GATE COMPANY STICKER (SPECAIL TYPE) <i>new</i>	1	\$ 800.00	\$ 800.00 <i>400</i>
5	TAIL GATE COVER (ALUMINIUM) <i>Best</i>	1	\$ 1,200.00	\$ 1,200.00 <i>400</i>
6	SIDE GATE COVER (ALUMINIUM) <i>new</i>	1	\$ 1,800.00	\$ 1,800.00 <i>+</i>
7	SIDE GATE COMPANY STICKET(SPECAIL TYPE) <i>new</i>	1	\$ 1,000.00	\$ 1,000.00 <i>400</i>
8	CARGO BED FLOOR PANEL(ALUMINIUM) <i>new</i>	1	\$ 2,800.00	\$ 2,800.00 <i>+</i>
9	PROBATIONARY LICENCE PLATE <i>new</i>	1	\$ 80.00	\$ 80.00 <i>25</i>
10	REAR END PENEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
11	REVERSE CAMERA <i>2nd</i>	1	\$ 550.00	\$ 550.00 <i>400</i>
12	REVERSE SENSOR (SET) <i>2nd</i>	1	\$ 220.00	\$ 220.00 <i>200</i>

1945

TOTAL \$ 8,730.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 2,200.00	<i>1000</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,800.00	<i>700</i>
3	REMOVE AND REFIX REAR CANOPY	\$ 600.00	<i>X.</i>
4	TO LIGHT UP CARGO BED	\$ 650.00	<i>X</i>
5	REMOVE AND REFIX REVERSE SENSOR	\$ 80.00	<i>50</i>
6	REMOVE AND REFIX TAIL GATE AND SIDE GATE ALUMINIUM COVER	\$ 800.00	<i>100</i>
7	REMOVE AND REFIX REAR FLOOR AUMINIUM	\$ 650.00	<i>X.</i>
8	REAR CHASSIS ALIGHMENT	\$ 250.00	<i>X</i>

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **YQ6010X**
MODEL : **TOYOTA DYNA**
DATE OF ACCIDENT : 29.04.2023
TIME OF ACCIDENT : 08:45 HOURS

9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
---	---	-----------	---

TOTAL \$ **7,030.00**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 19,015.35
TOTAL LABOUR COST : \$ 7,030.00
TOTAL REPAIR COST : \$ 26,045.35

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian L
1/s 04/05/23.
06 Days.

total: 908380
1/s: 7250

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: