

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	DMCVSNA00006712303	Date of Loss:	18/04/2023
Vehicle Reg. No.:	YP7543Z	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	double-trans pte ltd		
Make/Model:	HINO XZU710R-HKFMS3, 4.0 D (M)	Vehicle Reg. Date:	17/10/2017
Vehicle Colour:	White/Pearl	Chassis No:	JHHUCS3H50K02268
Engine No:	N04CUS34558		
Odometer:	66762 KM		
Paint Type:			<i>Not with in 11 Day @ ? Resurvey After Paint Est @ 1500h</i>
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	28 <i>18day</i>		
Present Location:	AH KENG MOTOR PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	27,853.13
Miscellaneous Items	0.00
Labour	19,000.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	46,853.13
+ GST 8.00% (S\$)	3,748.25
Nett Amount (S\$)	50,601.38

This claim is handled by: JEE MENG HENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 May 2023)
 Parts: N/A HINO XZU710R-HKFMS3 4.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Keng Motor Pte Ltd/YP7543Z/08/05/2023 13:01
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Front bumper	10.00	0.00	*795.00 FL	✓
2	1		*Front bumper bracket	10.00	0.00	*160.20 FL	✓
3	1		*Front grill	10.00	0.00	*710.00 FL	✓
4	1		*Front grill emblem	10.00	0.00	*81.40 FL	✓
5	1		*Front panel	10.00	0.00	*1,336.00 FL	✓
6	1		*Front panel inner	10.00	0.00	*2,196.00 FL	X
7	1		*Front panel Hino emblem	10.00	0.00	*60.00 FL	✓
8	1		*Front panel 300 emblem	10.00	0.00	*60.00 FL	✓
9	1		*Front panel Double-trans Pte Ltd sticker	0	0.00	*200.00 FS	?
10	1		*Front wiper panel	10.00	0.00	*942.00 FL	X
11	1		*Front right side side panel garnish	10.00	0.00	*862.40 FL	X
12	1		*Front right side door pillar (inner)	10.00	0.00	*780.00 FL	X
13	1		*Front right side door pillar (Lower)	10.00	0.00	*540.00 FL	X
14	1		*Front windscreen moulding	0	0.00	*209.00 FS	✓
15	1		*Front windscreen sealant	0	0.00	*120.00 FS	X
16	1		*Front cabin right side & left side mounting	10.00	0.00	*560.20 FL	?
17	1		*Front cabin roof lining	10.00	0.00	*1,120.00 FL	✓
18	1		*Front left side door	10.00	0.00	*1,310.75 FL	✓
19	1		*Front left side door weatherstrip	10.00	0.00	*261.20 FL	✓
20	1		*Front left side door hinges (Upper & Lower)	10.00	0.00	*226.80 FL	X
21	1		*Front left side door lock	10.00	0.00	*665.50 FL	?
22	1		*Front left side door checker	10.00	0.00	*110.00 FL	X
23	1		*Front left side door window regulator	10.00	0.00	*483.40 FL	?
24	1		*Front left side door window motor	10.00	0.00	*485.40 FL	?
25	1		*Front left side door window seal (Outer)	10.00	0.00	*152.80 FL	✓
26	1		*Front left side door 616 emblem	10.00	0.00	*60.00 FL	✓
27	1		*Front left side door Euro 5 emblem	10.00	0.00	*60.00 FL	✓
28	1		*Front left side door company logo	0	0.00	*200.00 FS	?
29	1		*Front reg. no. plate	0	0.00	*45.00 FS	✓
30	1		*Front left side rim	10.00	0.00	*800.00 FL	?
31	1		*Front left side rim tyre	10.00	0.00	*400.00 FL	?
32	1		*Front axle	10.00	0.00	*5,450.20 FL	?
33	1		*Front steering rack	10.00	0.00	*2,740.50 FL	?
34	1		*Front anti roll bar	10.00	0.00	*610.50 FL	?
35	1		*Front left side shock absorber	10.00	0.00	*450.00 FL	?
36	1		*Front right side kunckle	10.00	0.00	*910.40 FL	?
37	1		*Front right side bearing	10.00	0.00	*330.20 FL	?
38	1		*Front right side ABS sensor	10.00	0.00	*232.40 FL	?
39	1		*Rear wooden carridge	0	0.00	*7,000.00 FS	✓
40	1		*Rear LTA rear guard	0	0.00	*1,400.00 FS	✓

F=Franchise part. S=SpocNett. L=ListItemDisc.

Sub Total (\$\$)	35,117.25
- List Item Discount on L Items (\$\$) (-10%)	2,594.33
- Add. Disc. on L,N Items 20.00% (\$\$) (-20%)	4,669.79
Total Parts (\$\$)	27,853.13

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To dismantle, refit & repair damaged parts	New	4,000.00
2	To spray painting	New	2,800.00
3	To repair engine	New	10,000.00
4	To remove and replace front right side door	New	100.00
5	To remove and refit front windscreen	New	200.00
6	To check for wheel alignment	New	300.00
7	To remove and replace front under carriage	New	500.00
8	To re-seal anti-rust	New	300.00
9	To check wiring	New	800.00
Gross Labour Cost (S\$)			19,000.00

Ah Keng Motor Pte Ltd/YP7543Z/08/05/2023 13:01. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >