

SIN YU SIN WORKSHOP

1 KAKI BUKIT AVENUE 6
#01-82 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : GBJ2673T
VEHICLE MODEL : TOYOTA HIACE
CHASSIS NO : JTFHT02PX00247571

TP China.
Xin Yu

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>from</i>	1	\$ 541.20	\$ 541.20
2	FRONT BUMPER SIDE HOLDER <i>could</i>	1	\$ 66.50	\$ 66.50
3	FRONT BUMPER SIDE GRILLE <i>lib</i>	1	\$ 62.10	\$ 62.10
4	HEADLAMP <i>could</i>	1	\$ 745.20	\$ 745.20
5	AIR CLEANER BOX <i>could</i>	1	\$ 637.40	\$ 637.40
6	FRONT DOOR <i>parts</i>	1	\$ 1,438.50	\$ 1,438.50
7	FRONT DOOR LOCK <i>2 pps</i>	1	\$ 282.50	\$ 282.50
8	FRONT DOOR WEATHERSTRIPE <i>new</i>	1	\$ 281.50	\$ 281.50
9	FRONT DOOR HINGE LOWER	1	\$ 131.10	\$ 131.10
10	FRONT STEP PANEL GARNISH <i>new</i>	1	\$ 220.50	\$ 220.50

TOTAL PRICE: \$ 4,406.50

LESS 25% \$ 1,101.62

SUB TOTAL PRICE: \$ 3,304.88

2052.40
1539.30

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	FRONT DOOR COMPANY ADDRESS STICKER <i>new</i>	1	\$ 30.00	\$ 30.00
3	FRONT STEP PANEL GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00

TOTAL : \$ 80.00

60

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 800.00	<i>400</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 700.00	<i>400</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>30</i>	
5	TO TRANSFER FRONT DOOR FITTINGS	\$ 150.00	<i>x</i>	

\$ 1,850.00 *860*

ESTIMATE REPORT

TOTAL PARTS COST: \$ 3,384.88

TOTAL LABOUR COST: \$ 1,850.00

TOTAL REPAIR COST: \$ 5,234.88

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

FAX:

total: 2459.30

h/s: 1950

24 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: