



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 5903X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	263.50	-
1	REAR DOOR -RH	TO REPAIR SEE LABOUR	2,065.00	-
1	REAR DOOR INNER TRIM BOARD	NOT NECESSARY	1,585.00	-
1	REAR DOOR INNER LOCK	NOT NECESSARY	615.00	-
1	REAR DOOR OUTER HANDLE	NOT NECESSARY	405.00	-
1	REAR DOOR RUBBER	NOT NECESSARY	192.00	-
1	REAR FENDER -RH	TO REPAIR SEE LABOUR	2,495.00	-
1	REAR FENDER INNER SHIELD	NOT NECESSARY	189.00	-
1	REAR WHEEL BEARING	NOT NECESSARY	221.00	-
1	REAR WHEEL HUB	NOT NECESSARY	382.00	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	896.00	-
1	REAR KNUCKLE ARM	NOT NECESSARY	1,282.00	-
1	REAR LOWER ARM	NOT NECESSARY	786.00	-
1	REAR TOP ARM	NOT NECESSARY	332.00	-
	LESS 5% DISCOUNT		-585.43	-
			11,123.07	-
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET REAR FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	80.00	-
1	REAR TYRE (SN)	NOT NECESSARY	650.00	-
1	REAR WHEEL RIM -RH (SN)	SERVICEABLE	1,300.00	-
			2,110.00	-
<u>LABOUR</u>				
	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT INNER GARNISHES.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT REAR UNDERCARRIAGE.	NOT NECESSARY	400.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	200.00	-

Report Ref No. CS/SMR23004717/Uwy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.	NOT NECESSARY	200.00	-
	TO APPLY UNDERCOATING.	NOT NECESSARY	150.00	-
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR DOOR -RH AND REAR FENDER -RH.		1,600.00	500.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,500.00	500.00
			4,310.00	1,000.00
GRAND TOTAL			17,543.07	1,000.00
RECOMMENDED COST OF REPAIRS				1,000.00

Report Ref No. CS/SMR23004717/Uwy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.