

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III23004718/KYA3Q2**Date:** 08/06/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0009952
Claimant Vehicle No : SDH50R **Insured Vehicle No :** SNK4585D
 Date of Loss: 29/04/2023 Nature of Claim: TP Claim No: MFL2023D0004911

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDH50R**
 Make & Model: AUDI Q7, 3.0 TFSI QU (333 BHP) (A) Engine No: CRE048818
 Reg. Date: 30/09/2015 (Man. Year: 2015) Chassis No: WAUZZZ4M7GD011897
 Colour: Metallic Black Odometer: 124606 km
 Engine Capacity: 2995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 285/35Z R22 Rear Tyre Size: 285/35Z R22
 Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm
 Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/05/2023
 Date Inspected: 09/05/2023 Inspected At: K Kim Hin Auto Pte Ltd (HQ)
 160 Sin Ming Drive #02-20, Sin Ming AutoCity
 Singapore 575722
 Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$116,000.00

LTA REIMBURSEMENT VALUE (RV) : \$73,974.00

NETT VALUE : \$42,026.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jun 2023)
Parts:	M1-SUV	AUDI Q7 3.0 TFSI QU (333 BHP) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDH50R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >