

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

No. : 32917

Vehicle Insured : SNK 4585 D

Accident Date : 29-Apr-2023

Date : 08-May-2023

Our Ref : 023251 (III) / THERESA

PAGE : 1

YEO KHEE YEOW ANTHONY (MR)

Singapore

ESTIMATED COST OF REPAIR FOR AUDI Q7 3.0 TFSI QU (2015) SDH50R

=====

- 1 pc front number plate base
garnish
- 1 pc front bumper
- 1 pc front bumper lower diffuser
- 1 pc front bumper under cover
- 2 pcs front bumper lower side
skirting (LH/RH)
- 2 pcs front bumper rubber lid(LH/RH)
- 2 pcs front bumper side bracket
(LH/RH)
- 2 pcs front bumper inner air guide
(LH/RH)
- 2 pcs front bumper inner air guide
bracket (LH/RH)
- 1 pc front bumper towing cover
- 6 pcs front bumper parking sensor
bracket
- 1 pc RH front bumper parking sensor
-outer
- 1 pc RH front bumper parking sensor
-centre
- 1 pc front bumper parking sensor
wireharness
- 1 pc RH front bumper fog cover
- 1 pc front bumper centre bracket
- 1 pc front bumper parking sensor
seal
- 1 pc front grille
- 1 pc front grille moulding
- 1 pc front grille logo base
- 1 pc front grille inner bracket
- 1 pc front grille inner base

Con't Page 2 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SNK 4585 D
Our Ref : 023251

Page : 2
No. : 32917

2 pcs front grille parking sensor
(LH/RH)
2 pcs front grille parking sensor
bracket (LH/RH)
1 pc front grille camera
1 pc front grille camera bracket-
inner
1 pc front grille camera bracket-
outer
1 pc front grille camera cover
1 pc front bumper sponge
1 pc front bumper reinforcement
1 pc front bumper reinforcement
top air guide
2 pcs front bumper reinforcement
top support (LH/RH)
2 pcs front bumper side retainer
(LH/RH)
1 pc front support panel
2 pcs front support panel lower
support (LH/RH)
2 pcs front support panel lower side
member (LH/RH)
2 pcs front support panel lower side
member bracket (LH/RH)
2 pcs headlamp panel (LH/RH)
1 pc front support panel top
garnish - centre
2 pcs front support panel top side
garnish- outer (LH/RH)
2 pcs front support panel top side
garnish - inner (LH/RH)
2 pcs headlamp assy (LH/RH)
2 pcs headlamp control unit (LH/RH)
2 pcs headlamp adjusting screw
(LH/RH)
2 pcs headlamp nozzle (LH/RH)
2 pcs headlamp nozzle cover (LH/RH)
1 pc headlamp nozzle hose

Con't Page 3 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SNK 4585 D
Our Ref : 023251

Page : 3
No. : 32917

- 1 pc wiper washer tank
- 2 pcs wiper washer tank motor
- 2 pcs wiper washer tank motor bush
- 1 pc wiper washer tank neck
- 1 pc wiper washer tank neck cap
- 2 pcs horn
- 2 pcs front fender (LH/RH)
- 1 pc RH front fender inner bracket-front
- 1 pc RH front fender inner bracket-centre
- 1 pc RH front fender inner bracket-rear
- 1 pc RH front fender inner shield-front
- 1 pc RH front fender inner shield-rear
- 2 pcs front fender inner shield under cover (LH/RH)
- 2 pcs front fender 'S-line' emblem (LH/RH)
- 2 pcs front fender wheel arch garnish (LH/RH)
- 1 pc RH front door protector
- 1 pc engine under cover
- 1 pc bonnet
- 1 pc bonnet
- 2 pcs bonnet hinges (LH/RH)
- 2 pcs bonnet hinges actuator (LH/RH)
- 2 pcs bonnet inner seal
- 2 pcs bonnet lock (LH/RH)
- 2 pcs bonnet lock catch (LH/RH)
- 1 pc bonnet lock cable centre
- 1 pc bonnet lock cable centre cover
- 1 pc bonnet lock pull cable
- 1 pc bonnet safety lock cable
- 1 pc bonnet safety lock level
- 1 pc bonnet damper
- 1 pc bonnet damper ball stud

Con't Page 4 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SNK 4585 D
Our Ref : 023251

Page : 4
No. : 32917

- 1 pc bonnet insulator
- 10 pcs bonnet insulator clips
- 1 pc front windscreen glass
- 1 pc front windscreen glass
moulding
- 2 pcs front windscreen glass side
moulding (LH/RH)
- 2 pcs front windscreen glass side
moulding bracket (LH/RH)
- 2 pcs front windscreen glass side
moulding clips (LH/RH)
- 1 pc steering air bag
- 1 pc steering clock spring
- 1 pc front passenger airbag
- 1 pc dasbboard
- 1 pc driver seat belt
- 1 pc driver seat belt buckle
- 1 pc front passenger seat belt
- 1 pc front passenger seat belt
buckle
- 2 pcs roof top air bag (LH/RH)
- 1 pc roof top lining
- 1 pc battery '+' terminal c/w cut
off switch
- 3 pcs front airbag sensor
- 1 pc front pressure sensor
- 1 pc airbag control unit
- 2 pcs front pillar inner trim(LH/RH)
- 2 pcs centre pillar inner trim-top
(LH/RH)
- 2 pcs centre pillar inner trim -
bottom (LH/RH)
- 1 pc air con condenser
- 1 pc air con condenser pressure
sensor
- 1 pc air con condenser liquid pipe
- 1 pc air con condenser discharge
pipe
- 1 pc air con condenser suction pipe

Con't Page 5 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SNK 4585 D
Our Ref : 023251

Page : 5

No. : 32917

1 pc radiator-inner
1 pc radiator-outer
1 pc radiator top hose
1 pc radiator bottom hose
2 pcs radiator fan assy (LH/RH)
1 pc radiator fan cowling
1 pc radiator air guide - top
1 pc radiator air guide- bottom
2 pcs radiator air guide (LH/RH)
1 pc radiator shutter
2 pcs radiator shutter bracket
(LH/RH)
1 pc air intake duct
1 pc air cleaner box
1 pc air intake hose
1 pc engine top cover
1 pc inter cooler
1 pc RH inter cooler hose
1 pc RH inter cooler pipe
1 pc high pressure fuel pump
1 pc high pressure fuel pump inlet
pipe-top
1 pc high pressure fuel pump inlet
pipe-bottom
1 pc high pressure fuel pump outlet
pipe
1 pc rear bumper- top
1 pc rear bumper - centre
1 pc rear bumper - bottom
1 pc rear bumper centre moulding
2 pcs rear bumper towing cover
(LH/RH)
2 pcs rear bumper lamp (LH/RH)
1 pc RH rear bumper parking sensor-
inner
1 pc RH rear bumper parking sensor-
centre
1 pc RH rear bumper parking sensor-
outer

Con't Page 6 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SNK 4585 D
Our Ref : 023251

Page : 6
No. : 32917

2 pcs rear bumper parking sensor
bracket - outer
4 pcs rear bumper parking sensor
bracket-inner
2 pcs rear bumper side bracket
(LH/RH)
2 pcs rear bumper side retainer
(LH/RH)
1 pc rear bumper centre bracket
1 pc rear bumper lower bracket
1 pc rear bumper reinforcement
1 pc rear bumper cross member
6 pcs rear bumper parking sensor
seal
1 pc rear end panel- inner
1 pc rear end panel - outer
1 pc rear end panel top garnish
2 pcs taillamp assy (LH/RH)
1 pc RH taillamp panel - top
1 pc RH taillamp panel - bottom
1 pc RH rear fender
1 pc RH rear fender top glass
1 pc RH rear fender inner shield
2 pcs rear bumper wheel arch garnish
(LH/RH)
1 pc RH rear fender wheel arch
garnish
1 pc RH rear door wheel arch
garnish
1 pc RH rear door protector
1 pc RH rear fender inner trim-
bottom
2 pcs rear fender inner trim-top
(LH/RH)
1 pc tailgate
1 pc tailgate lock
1 pc tailgate lock cover
1 pc tailgate damper
1 pc tailgate inner trim-bottom

Con't Page 7 ...

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6452 5895

Vehicle Insured : SNK 4585 D
Our Ref : 023251

Page : 7
No. : 32917

1 pc tailgate logo
1 pc tailgate 'Q7' emblem
1 pc tailgate 'TFSI' emblem
1 pc tailgate 'quattro' emblem
1 pc rear exhaust muffler
1 pc RH rear exhaust chrome pipe
1 pc rear exhaust muffler heat
shield - top
1 pc rear exhaust muffler heat
shield - rear
1 pc RH rear exhaust heat shield
1 pc centre exhaust muffler
1 pc RH front rim
1 pc RH front shock absorber
1 pc RH front shock absorber
mounting
1 pc RH front shock absorber
stopper
1 pc RH front shock absorber cover
1 pc RH front shock absorber fork
1 pc RH front upper arm - front
1 pc RH front upper arm - rear
1 pc RH front upper arm bracket
1 pc RH front knuckle arm
1 pc RH front wheel bearing
1 pc RH front lower arm
1 pc RH front lower control arm
1 pc front stabilizer bar
1 pc RH front stabilizer bar
linkage
1 pc RH front tie rod
1 pc RH front tie rod eng
1 pc steering rack & pinion
1 pc RH rear rim
1 pc RH rear shock absorber assy
1 pc RH rear air suspension spring
1 pc RH rear lower arm
1 pc RH rear lower control arm
1 pc rear stabilizer bar

Con't Page 8 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SNK 4585 D
Our Ref : 023251

Page : 8
No. : 32917

1 pc	RH rear stabilizer bar linkage		
1 pc	RH rear trailing arm		
1 pc	RH rear upper arm		
1 pc	RH rear upper control arm		
1 pc	RH rear knuckle arm		
1 pc	RH rear wheel bearing		
1 pc	RH rear parking brake caliper		
1 pc	RH rear charcoal canister assy		
1 pc	RH rear charcoal canister under cover		
1 pc	RH rear charcoal canister bracket		
1 pc	RH rear charcoal canister inlet hose		
1 pc	RH rear charcoal canister outlet hose		
1 pc	RH rear charcoal canister sensor		
1 pc	front number plate	40.00	sn
1 pc	RH headlamp wireharness	280.00	sn
1 pc	front windscreen glass sealant	40.00	sn
1 pc	front windscreen glass damping seal	20.00	sn
1 pc	front windscreen glass solar film	200.00	sn
1 pc	ERP bracket	26.00	sn
1 pc	radiator coolant	48.00	sn
1 pc	rear number plate	40.00	sn
1 pc	RH rear fender top glass sealant	40.00	sn
1 pc	RH rear fender top glass damping seal	20.00	sn
1 pc	RH front tyre	480.00	sn
1 pc	RH rear tyre	480.00	sn
1 pc	tailgate windscreen sealant	40.00	sn
1 pc	tailgate windscreen damping seal	20.00	sn

Con't Page 9 ...

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Road #02-18/19/20

Singapore AutoCity

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SNK 4585 D
Our Ref : 023251

Page : 9
No. : 32917

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	2,700.00
To focus Headlamps and Taillamps.	
To check front and rear lighting operation and rewiring	60.00
To remove and renew front wind- screen glass and conduct water leak test.	120.00
To remove and renew rear windscreen glass and conduct water leak test.	120.00
To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works	120.00
To remove and refit front seat assy trim board and carpet to facilitate repairing works	120.00
To remove aircon condenser, pipes and driers. Vaccum and recharge gas	100.00
To apply undersealing	180.00
To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.	280.00
To remove and renew air bag sensors seat belts assy, to rewiring and re-setting program	380.00

Con't Page 10 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SNK 4585 D
Our Ref : 023251

Page : 10
No. : 32917

To dismantle and check front under-carriages. To replace affected portions.	240.00
To dismantle and check rear under-carriage. To replace affected portions.	240.00
To conduct front wheel alignment test.	100.00
To check and realignment on chassis member.	380.00
To remove and renew exhaust silencer box	160.00
To transfer tailgate's fittings	120.00
To remove and refit reverse sensor assy.	100.00
To putty and respray on affected portions.	2,800.00
Total :	----- S\$10,094.00 =====

Singapore Dollars Ten Thousand and Ninety Four
Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.