

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SGG 1006H
 TP/AG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

ATTN: Motor Claim Department

FAX: 64153727

Estimate No: ES2300478

Date: 09 May 2023

Policy No:

Veh Reg No: SGG1006H

Make/Model: TOYOTA

LEXUS NX200T
 EXECUTIVE

WS Ref:

TP AIG

Claim Type:

Third Party

Accident Date:

08/05/2023

Chassis No: JTJBARBZ202117442

Engine No:

Reg. Date: 21/09/2017

Estimate Repair Cost to Vehicle No :SGG1006H

PAGE:1/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT BUMPER	1,269.60	1 PC	1,269.60	
2 FRONT BUMPER SIDE RETAINER	150.80	1 PC	150.80	
3 FRONT BUMPER FOG LAMP LH	1,109.30	1 PCS	1,109.30	
4 FRONT BUMPER FOG LAMP GARNISH LH	132.50	1 PC	132.50	
5 FRONT BUMPER PARKING SENSOR LH	546.10	1 PC	546.10	
6 FRONT BUMPER CLIP	5.50	6 PCS	33.00	
7 DAY LIGH LH	2,208.80	1 PC	2,208.80	
8 HEADLAMP LH	1,491.60	1 PC	1,491.60	
9 HEADLAMP ECU LH	1,085.40	1 PC	1,085.40	
10 HEADLAMP WIPER NOZZLE LH	564.00	1 PC	564.00	
11 FRONT LH FENDER	1,721.00	1 PC	1,721.00	
12 FRONT LH FENDER INNER SHIELD	210.15	1 PCS	210.15	
13 FRONT LH FENDER INNER SHIELD CLIP	5.00	6 PCS	30.00	
14 FRONT LH WHEEL ARP GARNISH	297.90	1 PC	297.90	
15 LH SIDE SKIRT (FRT)	439.10	1 PC	439.10	
16 LH SIDE SKIRT (REAR)	315.20	1 PC	315.20	
17 RERA LH WHEEL ARP GARNISH	168.10	1 PC	168.10	
18 REAR BUMPER	770.00	1 PC	770.00	
19 REAR BUMPER SIDE RETAINER LH	110.10	1 PC	110.10	
20 REAR BUMPER CLIP	5.50	6 PC	33.00	
21 REAR BUMPER LOWER	426.30	1 PC	426.30	
22 FRONT LH SPORT RIM	3,617.90	1 PC	3,617.90	
23 FRONT LH KNUCKLE ARM	796.70	1 PC	796.70	
24 FRONT LH WHEEL BEARING	698.20	1 PC	698.20	
25 FRONT LH SHOCK ABSORBER TOP MOUNTING	894.80	1 PC	894.80	
26 FRONT LH DRIVESHAFT	1,791.30	1 PC	1,791.30	
27 FRONT LH LOWER ARM	1,104.80	1 PC	1,104.80	
28 STEERING RACK & PINION	2,304.20	1 PC	2,304.20	
			24,319.85	
		Less 25%	6,079.96	18,239.89
Labour				
29 TOWING	100.00	1 LA	100.00	601
30 TO REMOVE AND REFIX FRT BUMPER ASSY, HEADLAMP, FOG LAMP, DAYLIGHT, FR TLH FENDER, KNOCK AND REPAIR FRT SUPPORT PANEL, BONNET & RE-ALIGN THE SAME	700.00	1 LA	700.00	501

Not authorized
1/1/2023
Perovoy Abu Pain

not done

601
501

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
ES2300478/YISHUN
 #07-16 AIG BUILDING
 SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department

Estimate No: ES2300478
Date: 09 May 2023
Policy No:
Veh Reg No: SGG1006H
Make/Model: TOYOTA TOYOTA
 LEXUS NX200T
 EXECUTIVE
Chassis No: JTJBARBZ202117442
Engine No:
Reg. Date: 21/09/2017

WS Ref: TP AIG
Claim Type: Third Party
Accident Date: 08/05/2023

Estimate Repair Cost to Vehicle No :SGG1006H

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
31 TO REMOVE AND REFIX REAR BUMPER, KNOCK AND REPAIR RR PANEL, RR LH FENDER AND RE-ALIGN TO SAME	500.00	1 LA	500.00	250
32 TO REMOVE AND REFIX FRT LH UNDERCARRAIGE, STTERING RACK & PINION, DRIVESHAFT	380.00	1 LA	380.00	320
33 PUTTY AND RESPRAY ON FRT & RR BUMPERS, FRT & RR LH FENDERS, FRT & RR LH DOROS, BONNET & SUPPORT	1,500.00	1 LA	1,500.00	1200
34 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	80.00	1 PC	80.00	60
35 RUSTPROOFING	60.00	1 LA	60.00	30
			3,320.00	3,320.00
			Total	S\$ 21,559.89
			Add GST @ 8%	1,724.79
			Total Amount Payable	S\$ 23,284.68

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____