

Your Ref : CDMPG23001099

Date: 16th May 2023

Our Ref : CS/EGI23004723/Rvy3m4

M/s Ergo Insurance Pte Ltd

8 Temasek Boulevard

#04-01 Suntec Tower Three

Singapore 038988

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMF 8988L
ACCIDENT ON 04/05/2023**

Instruction was received to inspect the vehicle Reg. No. SMF 8988L. The inspection was conducted on 09/05/2023 at the premises of M/s Borneo Motors (S) Pte Ltd, 2 Pandan Crescent, Singapore 128462.

The following vehicle information was recorded:

Registration Number	: SMF 8988L
Make/Model	: Toyota Lexus Rx300 5DR SUV (AT) (4wd) Luxury
Year of Registration	: 2018
Body Colour	: White
Chassis Number	: JTJBAMCA802060157
Engine Capacity	: 1998 cc

The vehicle sustained damages at the front, rear o/s portion and o/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 160,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 72,334.00)
Nett Liability	<u>S\$ 87,666.00</u> =====

Vehicle Inspected By:



MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.