



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: TEO KITTY			Ref: CS/HSB23004729/Uvp3m4 Date: 20/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 6719D	Veh. Inspected	SMM 2688E
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M045D7	Excess (\$)	0.00
	Assign From	TEO KITTY	Assign Date	09/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CLA180 AMG LINE (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WDD1173422N143282	Colour	PURPLE
	Odometer	58143 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40R18	PIRELLI	6 mm
	L/H Front Tyre	225/40R18	PIRELLI	6 mm
	R/H Rear Tyre	225/40R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/40R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/06/2022	Inspection Date	08/06/2023
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	