51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Immediate Advice

To: HSBC Life (Singapore) Pte Ltd DATE: 17/07/2023

Survey details

Date of loss	3/5/2023
Date of appointment	9/5/2023
Date of survey	10/5/2023
Location of survey	LAM AUTO PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	GBH 1043D
Make and Model	TOYOTA DYNA 150 5MT
Date of registration	10/1/2018
Excess	
Market Value	\$70,000.00
Parf Rebate	\$10,194.00
Nett Loss	\$59,806.00

Repair details

la sur same un	
Initial Estimate	
mittai Estimate	

Proposed/Revised repair cost:

Parts		
"Check items (Estimated)		
Labour		
Total		
Lump Sum (Estimated)		
Number of days of repair	3 days (est)	

Remarks:

Damages Consistent.

The estimate repair cost of the damaged vehicle is in the region of \$1,500.00 to \$2,000.00