



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23004734/Avy3e2	
			Date: 04/07/2023	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 1519A	Veh. Inspected	SMQ 8659D
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/05/23/5009	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	09/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GK82100270	Colour	SILVER
	Odometer	97748 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	GITI	6 mm
	L/H Front Tyre	185/60 R15	GITI	6 mm
	R/H Rear Tyre	185/60 R15	GITI	6 mm
	L/H Rear Tyre	185/60 R15	GITI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/05/2023	Inspection Date	08/05/2023
	Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	