



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD  
16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING  
SINGAPORE 048581

Ref: CS/FCI23004735/Tqy3m4

Date: 24/07/2023

Code: FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	RU 4398C	<b>Veh. Inspected</b>	SLQ 2147R
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D23001608MFCV	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JOANNE TAN	<b>Assign Date</b>	09/05/2023

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	SUBARU OUTBACK	<b>c.c</b>	2498
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	JF2BS9KC2GG046434	<b>Colour</b>	SILVER
<b>Odometer</b>	89327 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/60 R18	PIRELLI	6 mm
<b>L/H Front Tyre</b>	225/60 R18	PIRELLI	6 mm
<b>R/H Rear Tyre</b>	225/60 R18	PIRELLI	6 mm
<b>L/H Rear Tyre</b>	225/60 R18	PIRELLI	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	02/05/2023	<b>Inspection Date</b>	15/05/2023
<b>Survey held at</b>	25 LENG KEE ROAD SINGAPORE 159097		
<b>Repairer</b>	MOTOR IMAGE ENTERPRISES PTE LTD		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**