

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0127/2023
DATE : 08-MAY-2023

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : TEE KOK LIAN
ADDRESS : APT BLK 747 WOODLANDS CIRCLE
#11-702
S(730747)
TELEPHONE NO : 91270740

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700022097-05 AIG
VEHICLE NO : SLQ2147R
MODEL CODE : BS9BKLC
MODEL/YEAR : OUTBACK 2.5I-S AWD CVT
ENGINE NO : FB25Y526090
CHASSIS NO : JF2BS9KC2GG046434
MILEAGE : 1 KM
DATE IN : 08/05/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 08/05/2023

Print Date : 18/07/2023
Print Time : 08:53:51

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLQ2147R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST MS FIRST CAPITAL-INS		
2	ZZ/001	DOA:02/MAY/2023 TIME:1340 HRS LOCATION:37 JURONG PORT RD,S(619110)		
3	ZZ/002	REPLACE FRT BUMPER & REPAIR RH FENDER	3500.00	900.00
4	ZZ/003	RESPRAY FRT BUMPER & RH FENDER	3000.00	1040.00
5	ZZ/004	TO CONDUCT FRONT LIGHTING TEST	50.00	50.00
6	ZZ/005	REMOVE & REFIX FRONT HEADLAMP WASHER & PIPING	150.00	150.00
7	ZZ/006	FAULT DIAGNOSTIC (RESET)	280.00	280.00
8	ZZ/007	SUNDRIES	100.00	20.00
9	ZZ/008	REPAIR FRONT HOOD & RH SUPPORT PANEL (1.0)	600.00	600.00
10	ZZ/009	RESPRAY FRONT HOOD & SUPPORT PANEL (1.5)	780.00	780.00
		TOTAL LABOUR CHARGES	8460.00	3820.00

MOTORIMAGE ENTERPRISES PTE. LTD.
 25 LENG KEE ROAD
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLQ2147R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	FENDER F RH	57120AL0609P			277.50	X
2	FENDER F LH	57120AL0709P			277.50	X
3	HOOD COMPL F	57229AL0119P			740.00	X
4	COVER ASSY FEN UPRH	57256AL021			19.10	OK
5	COVER ASSY FEN UPLH	57256AL031			18.50	X
6	BUMPER PUNCHING F OBK FOR H/W	57702AL110			610.50	OK
7	ENR ABSORB FOAM FEXP	57705AL050			59.20	X
8	BRKT CORNER F FHIRH	57707AL060			33.30	OK
9	BRKT CORNER F FHILH	57707AL070			33.30	X
10	BRKT SD F RH	57707AL081			18.50	X
11	BRKT SD F LH	57707AL091			18.50	X
12	BEAM COMPL F EU	57711AL0109P			296.00	X
13	COVER HOOK F OBK FHI	57731AL170			5.60	X
14	FRONT RESIN UNDER GUARD OBK	57734AL000			270.00	X
15	LAMP ASSY HEAD RHS	84002AL000			1870.00	OK
16	LAMP ASSY HEAD RLA	84002AL010			1870.00	X
17	NOZZLE H L WASHERRH	86636AL011			92.50	X
18	NOZZLE H L WASHERLH	86636AL021			92.50	X
19	NOZZLE COVER ASSYOBR	86636AL070E2			55.50	X
20	NOZZLE COVER ASSYOBL	86636AL080E2			55.50	X
21	GRILLE ASSY F NA	91121AL060			703.00	X
22	ORNAMENT F 6KA	93013AL000			74.00	X
23	CARGO STEP RESIN	E775ESG000			420.00	X
SUB TOTAL			0.00	0.00	2532.90	0.00
LESS DISCOUNT ()			0.00	0.00	0.00	0.00

MOTORIMAGE ENTERPRISES PTE. LTD.
 25 LENG KEE ROAD
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLQ2147R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
	GRAND TOTAL		0.00	0.00	2532.90	0.00
	OVERALL TOTAL		2532.90			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLQ2147R

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	2532.90
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	3820.00
TOTAL SPARE PARTS CHARGES	2532.90

TOTAL CHARGES	6352.90
ADD 8 % GST	508.23

GRAND TOTAL	6861.13
