

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0127/2023
DATE : 08-MAY-2023

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : TEE KOK LIAN
ADDRESS : APT BLK 747 WOODLANDS CIRCLE
#11-702
S(730747)
TELEPHONE NO : 91270740

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700022097-05 AIG
VEHICLE NO : SLQ2147R
MODEL CODE : BS9BKLC
MODEL/YEAR : OUTBACK 2.5I-S AWD CVT
ENGINE NO : FB25Y526090
CHASSIS NO : JF2BS9KC2GG046434
MILEAGE : 1 KM
DATE IN : 08/05/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 08/05/2023

Print Date : 09/05/2023
Print Time : 09:24:03

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLQ2147R

| S/NO | JOB CODE | NATURE OF JOB | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|------|----------|--|-------------------|---------------------------|
| 1 | TPCLAIM | CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST MS FIRST CAPITAL-INS | | |
| 2 | ZZ/001 | DOA:02/MAY/2023 TIME:1340 HRS LOCATION:37 JURONG PORT RD,S(619110) | | |
| 3 | ZZ/002 | REPLACE FRT HOOD,FRT BUMPER,ENERGY ABSORBER,BUMPER BEAM,LH FENDER & RH FENDER | 3500.00 | |
| 4 | ZZ/003 | RESPRAY FRT HOOD,FRT BUMPER,BUMPER BEAM,LH FENDER & RH FENDER | 3000.00 | |
| 5 | ZZ/004 | TO CONDUCT FRONT LIGHTING TEST | 50.00 | |
| 6 | ZZ/005 | REMOVE & REFIX FRONT HEADLAMP WASHER & PIPING | 150.00 | |
| 7 | ZZ/006 | FAULT DIAGNOSTIC (RESET) | 280.00 | |
| 8 | ZZ/007 | SUNDRIES | 100.00 | |
| | | TOTAL LABOUR CHARGES | 7080.00 | |

MOTORIMAGE ENTERPRISES PTE. LTD.
 25 LENG KEE ROAD
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLQ2147R

| S/NO | PARTS DESCRIPTION | PARTS NUMBER | DAMAGED PARTS & PRICES | | | S/LIST REMARKS |
|------|-------------------------------|--------------|------------------------|------|---------|----------------|
| | | | NETT | LIST | S/NETT | |
| 1 | FENDER F RH | 57120AL0609P | | | 277.50 | |
| 2 | FENDER F LH | 57120AL0709P | | | 277.50 | |
| 3 | HOOD COMPL F | 57229AL0119P | | | 740.00 | |
| 4 | COVER ASSY FEN UPRH | 57256AL021 | | | 19.10 | |
| 5 | COVER ASSY FEN UPLH | 57256AL031 | | | 18.50 | |
| 6 | BUMPER PUNCHING F OBK FOR H/W | 57702AL110 | | | 610.50 | |
| 7 | ENR ABSORB FOAM FEXP | 57705AL050 | | | 59.20 | |
| 8 | BRKT CORNER F FHIRH | 57707AL060 | | | 33.30 | |
| 9 | BRKT CORNER F FHILH | 57707AL070 | | | 33.30 | |
| 10 | BRKT SD F RH | 57707AL081 | | | 18.50 | |
| 11 | BRKT SD F LH | 57707AL091 | | | 18.50 | |
| 12 | BEAM COMPL F EU | 57711AL0109P | | | 296.00 | |
| 13 | COVER HOOK F OBK FHI | 57731AL170 | | | 5.60 | |
| 14 | FRONT RESIN UNDER GUARD OBK | 57734AL000 | | | 270.00 | |
| 15 | LAMP ASSY HEAD RHS | 84002AL000 | | | 1870.00 | |
| 16 | LAMP ASSY HEAD RLA | 84002AL010 | | | 1870.00 | |
| 17 | NOZZLE H L WASHERRH | 86636AL011 | | | 92.50 | |
| 18 | NOZZLE H L WASHERLH | 86636AL021 | | | 92.50 | |
| 19 | NOZZLE COVER ASSYOBR | 86636AL070E2 | | | 55.50 | |
| 20 | NOZZLE COVER ASSYOBL | 86636AL080E2 | | | 55.50 | |
| 21 | GRILLE ASSY F NA | 91121AL060 | | | 703.00 | |
| 22 | ORNAMENT F 6KA | 93013AL000 | | | 74.00 | |
| | SUB TOTAL | | 0.00 | 0.00 | 7490.50 | 0.00 |
| | LESS DISCOUNT () | | 0.00 | 0.00 | 0.00 | 0.00 |
| | GRAND TOTAL | | 0.00 | 0.00 | 7490.50 | 0.00 |

MOTORIMAGE ENTERPRISES PTE. LTD.
 25 LENG KEE ROAD
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLQ2147R

DAMAGED PARTS & PRICES

| S/NO | PARTS DESCRIPTION | PARTS NUMBER | NETT | LIST | S/NETT | S/LIST REMARKS |
|---------------|-------------------|--------------|---------|------|--------|----------------|
| OVERALL TOTAL | | | 7490.50 | | | |

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLQ2147R

TOTAL LABOUR CHARGES 7080.00
TOTAL SPARE PARTS CHARGES 7490.50

GRAND TOTAL 14570.50 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.