

(08/11/13) Wef

ASS. REC. BY: John

REF:

CS/EH123004737/RJY3

250K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBJ 958Kat Workshop m/s MILLION AUTOof 4, Penman Rd #01-12Insured: EHI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 57K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBJ 958K Yr Regn: 2012 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HIACE VAN TURBO SOBM c.c 2982Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 256900 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTF HTD 2P 00246723

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195R15 LT

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GLENLANDER

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 07/05/23 D.O.I. 11/05/23Survey held at MILLION AUTODes. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 42K

Date/Time, File Pass to?



: Prell. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

) S + RS SI


) Photos

) Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL



萬汽車服務

MILLION AUTO SERVICE

No. 4 Penjuru Place #01-12, 2.8 Penjuru Tech Hub, Singapore 608782
 Website: <http://www.millionauto.com> Email: wendy@millionauto.com
 Tel: 6567 0817, 6264 9091 Fax: 6791 4716
 Reg No: 317413/00-K GST Reg No: M90363776

09-May-23

Ergo Insurance Pte Ltd
 5 Temasek Boulevard
 #04-05 Suntec Tower Five
 Singapore 038958

Without Prejudice

Atten Motor Claim Department

Dear Sir,

Vehicle No.: GBJ958K
 Chassis No.: JTFHT02P200246723

Model: TOYOTA Hiace Van Turbo 5Dr Mt
 Year: 2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR ESTIMATE

S/N	PARTS REPLACEMENT - LIST ITEM	Qty	Unit Price (S) \$	Price (S) \$
1	Tailgate assy <i>bl</i>	1	1,869.00	1,869.00
2	Tailgate outer garnish <i>ca</i>	1	322.00	322.00
3	Rear number plate lamp	2	167.20	334.00
4	Tailgate "TOYOTA" logo <i>new</i>	1	62.00	62.00
5	Tailgate lock <i>ca</i>	1	263.00	263.00
6	Tailgate lock cover <i>x</i>	1	98.90	98.90
7	Tailgate auto lock actuator <i>x</i>	1	485.80	485.80
8	Tailgate weatherstrip <i>de</i>	1	385.60	385.60
9	Tailgate inner trim board	1	443.20	443.20
10	Tail lamp R/L <i>ca</i> <i>new</i> <i>x</i>	21	352.70	705.40
11	Tail lamp inner seals R/L <i>x</i>	21	65.50	131.00
12	Tail lamp bottom corner garnish R/L <i>LH-X/RH-SCA</i>	21	157.10	314.20
13	Tail lamp bottom corner garnish retainers R/L <i>LH-X/RH-SCA</i>	21	53.00	106.00
14	Rear bumper <i>de</i>	1	498.50	498.50
15	Rear bumper lower brackets <i>bl</i>	2	53.20	106.40
16	Rear bumper side retainers <i>LH-X/RH-SCA</i>	21	65.50	131.00
17	Rear end panel inner <i>bl</i>	1	826.50	826.50
18	Rear end panel outer <i>bl</i>	1	342.50	342.50
19	Rear end panel top plate <i>x</i>	1	177.80	177.80
20	Rear spare tyre carriage bracket <i>x</i>	1	244.20	244.20
Sub Total:				7,847.00

Rasue
Hp 90010068
7 days
L/S
11/05/23 @ 1120
Ready after repair

PART REPLACEMENT - SPECIALNETT ITEMS

1	Rear bumper clips <i>new</i>	50.00	30
2	Tailgate inner trim board clips <i>new</i>	50.00	30
3	Rear windscreen inner seal <i>new</i>	50.00	360
4	Rear windscreen sealant <i>new</i>	60.00	
5	Rear number plate <i>bl</i>	50.00	35
6	Rear end panel sealant <i>new</i>	60.00	80
7	Tailgate 70KM/H sticker <i>new</i>	40.00	10
8	Tailgate 8 Pax sticker <i>new</i>	40.00	10
9	Rear bumper reverse sensors <i>new</i>	250.00	200
Sub Total:		650.00	

LABOUR AND MISCELLANEOUS CHARGES

1	Labour for panel beating, cut, weld, straighten affected area and replace damage parts.	1,200.00	800
2	To putty and spray painting to affected area	800.00	700
3	To apply anti rust proofing on affected area	150.00	80
4	To remove floor carpet and upholstery to assist to repair	200.00	80
5	To remove and transfer tailgate mechanism	150.00	80
6	To remove and install windscreen glass	200.00	120
7	To check and reset wiring function	80.00	40
8	To remove and install rear bumper reverse sensors	80.00	40
Sub Total:		2,860.00	

Enquire PARF/COE Rebate for Registered Vehicle

Owner Details	
Owner ID Type:	Business
Owner ID:	300K
Vehicle Details	
Vehicle No.:	GBJ958K
Vehicle to be Exported:	No
Intended Deregistration Date:	15 May 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1KD2833422
Chassis No.:	JTFHT02P200246723
Maximum Power Output:	-
Open Market Value:	\$28,136.00
Original Registration Date:	03 Jan 2019
First Registration Date:	03 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
Enquired PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Enquired COE Rebate Details	
COE Expiry Date:	02 Jan 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$26,026.00
COE Rebate Amount:	\$14,657.00
Total Rebate Amount:	\$14,657.00

The information contained herein is correct as at 15 May 2023

OK