



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HL ASSURANCE PTE LTD 11 KEPPEL ROAD #11-01 ABI PLAZASINGAPORE 089057			Ref: CS/HLA23004740/y3 Date: 09/05/2023 Code: HLA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMM 1721Z	Veh. Inspected	GBD 8776Y
	Policy No.	MP320415	Coverage (\$)	0.00
	Claim No.	MPC04161	Excess (\$)	0.00
	Assign From	GRACE NG	Assign Date	09/05/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	c.c 0		
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	Colour		
	Odometer	-	Steering	
	Brakes	Modification		
	General			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
	Accident Date	28/04/2023	Inspection Date	
	Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			