

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
S	STRIDES AUTOMOTIVE SERVICES PTE LTD		Ref:	CS3/SMR23003694/Uqy3e2-1	
	0 WOODLANDS II 4SINGAPORE 75	NDUSTRIAL PARK 7705	Date	: 07/06/2023	
			Code	e: SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM				
In	nsured Veh.	SMB 1605J	Veh. Inspected	GBK 2886R	
P	olicy No.		Coverage (\$)	0.00	
С	laim No.	BUS/03/23/5031	Excess (\$)	0.00	
Α	ssign From	HUA YEN	Assign Date	09/05/2023	
2. Vehicle Particulars & Condition					
M	lake & Model	MITSUBISHI L200 DOUBLE (M)	c.c	2442	
E	ingine No.	HIDDEN	Year of Reg.	2020	
С	hassis No.	MMCJJKL20KH007290	Colour	SILVER	
О	dometer	211226 KM	Steering	IN ORDER	
В	Brakes	IN ORDER	Modification	SPORTS RIM	
G	Beneral	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
R	H Front Tyre	205 R16	FALKEN	6 mm	
L	/H Front Tyre	205 R16	FALKEN	6 mm	
R	R/H Rear Tyre	205 R16	FALKEN	6 mm	
L	/H Rear Tyre	205 R16	FALKEN	6 mm	
4.	<u>-</u>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
D.	DAMAGES SEE DETAILS.				
5.	General Information				
Α	ccident Date	16/03/2023	Inspection Date	16/05/2023	
s	Survey held at	JIN AUTO SERVICES PTE LTD			
		BLK 14 DEFU LANE 10 #01-412			
		SINGAPORE 539195			
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
	. Estimate Days of Repair				
5b.			<u>'</u>		