

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road

Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email:

tanpw@cdge.com.sg;kelvinsukwen@cdge.com.sg;oisunpin@cdge.com.sg;joharibh@sparkcarcare.com;kristytay@sparkcarcare.com

TP INSURER:

TAN HOE ANN JACOB

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY

Policy No:

Ref. No:

Date of Loss: 23/04/2023

Vehicle Reg. No.:

SJP8998R

Driveable?

Party At Fault:

UNKNOWN

Make/Model:

HONDA ACCORD, 2.0 VTIS 5AT (A) Vehicle Reg. Date: 20/07/2016

Vehicle Colour:

WHITE

Engine No:

R20Z21600031

Chassis No:

MRHCR1630GP000011

Odometer:

0 KM

Paint Type:

NO

Total Loss?

Est. Duration of Repair
(day)

8 days

Not Withheld
11 Day @
Repair After Repair

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

COST OF CLAIMS

	Amount
Parts	7,303.67
Miscellaneous Items	11.00
Labour	1,880.00
Paintwork Labour	0.00
Painting	0.00

Gross Total (\$\$) 9,194.67

+ GST 8.00% (\$\$) 735.57

Nett Amount (\$\$) 9,930.24

is claim is handled by: PATRICK TIA JEE KIANG

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 May 2023)
Parts: 143 HONDA ACCORD 2.0 VTIS 5AT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SJP8998R/08/05/2023 13:57
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT LID	13	0.00	0.00 *1,314.56 F X
2	1		*REAR BOOT LID WEATHERSTRIP	13	0.00	0.00 *110.76 F X
3	1		*REAR BOOT LID LOCK	13	0.00	0.00 *151.06 F X
4	1		*REAR BOOT LID EMBLEM	13	0.00	0.00 *46.54 F X
5	1		*REAR BOOT LID ACCORD WORDING	13	0.00	0.00 *36.40 F 1
6	1		*REAR BUMPER	CM	0.00	0.00 *885.17 F 1
7	1		*REAR BUMPER REINFORCEMENT	CM	0.00	0.00 *436.80 F 7
8	10		*REAR BUMPER CLIP	13	0.00	0.00 *50.00 F 1
9	2		*REAR BUMPER SIDE RETAINER	13	0.00	0.00 *50.70 F 1
10	1		*REAR BUMPER CHROME MOULDING	13	0.00	0.00 *306.41 F 1
11	1		*REAR BUMPER REFLEXOR RH	13	0.00	0.00 *56.65 F 7
12	2/1		*REAR BUMPER SENSOR CENTER	13	0.00	0.00 *771.42 F 1
13	2		*REAR TAIL LAMP		0.00	0.00 *1,869.92 F ?
Sub Total (S\$)						6,086.39
+ Margin on L,N Items 20.00% (S\$)						1,217.28
Total Parts (S\$)						7,303.67

F=Franchise part.

ComfortDelGro Engineering Pte Ltd/SJP8998R/08/05/2023 13:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	201 100.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	801 120.00
3	PANEL BEATING,KNOCKING AND STRIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL PF PARTS , ADJUST AND REALIGN THE SAME	New	201 580.00
4	PUTTY AND SPARY PANTING OF THE AFFECTED PORTION.	New	2501 900.00
5	TO RUST PROOF THE AFFECTED AREAS.	New	121 180.00 X
Gross Labour Cost (S\$)			1,880.00

ComfortDelGro Engineering Pte Ltd/SJP8998R/08/05/2023 13:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >