

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road

Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email:

tanpw@cdge.com.sg;kelvinsukwen@cdge.com.sg;oisunpin@cdge.com.sg;joharibh@sparkcarcare.com;kristytay@sparkcarcare.com

TP INSURER: India International Insurance Pte Ltd (HQ)**TAN HOE ANN JACOB**

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/04/2023
Vehicle Reg. No.:	SJP8998R	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HONDA ACCORD, 2.0 VTIS 5AT (A)	Vehicle Reg. Date:	20/07/2016
Vehicle Colour:	WHITE		
Engine No:	R20Z21600031	Chassis No:	MRHCR1630GP000011
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

COST OF CLAIMS

	Amount
Parts	7,303.67
Miscellaneous Items	11.00
Labour	1,880.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,194.67
+ GST 8.00% (S\$)	735.57
Nett Amount (S\$)	9,930.24

This claim is handled by: PATRICK TIA JEE KIANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 May 2023)

Parts: 143 HONDA ACCORD 2.0 VTIS 5AT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SJP8998R/08/05/2023 13:57

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT LID	0.00	0.00	*1,314.56 F
2	1		*REAR BOOT LID WEATHERSTRIP	0.00	0.00	*110.76 F
3	1		*REAR BOOT LID LOCK	0.00	0.00	*151.06 F
4	1		*REAR BOOT LID EMBLEM	0.00	0.00	*46.54 F
5	1		*REAR BOOT LID ACCORD WORDING	0.00	0.00	*36.40 F
6	1		*REAR BUMPER	0.00	0.00	*885.17 F
7	1		*REAR BUMPER REINFORCEMENT	0.00	0.00	*436.80 F
8	10		*REAR BUMPER CLIP	0.00	0.00	*50.00 F
9	2		*REAR BUMPER SIDE RETAINER	0.00	0.00	*50.70 F
10	1		*REAR BUMPER CHROME MOULDING	0.00	0.00	*306.41 F
11	1		*REAR BUMPER REFLEXTOR RH	0.00	0.00	*56.65 F
12	2		*REAR BUMPER SENSOR CENTER	0.00	0.00	*771.42 F
13	2		*REAR TAIL LAMP	0.00	0.00	*1,869.92 F
F=Franchise part.						
Sub Total (\$\$)						6,086.39
+ Margin on L,N Items 20.00% (\$\$)						1,217.28
Total Parts (\$\$)						7,303.67

ComfortDelGro Engineering Pte Ltd/SJP8998R/08/05/2023 13:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00
3	PANEL BEATING,KNOCKING AND STRIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL PF PARTS , ADJUST AND REALIGN THE SAME	New	580.00
4	PUTTY AND SPARY PANTING OF THE AFFECTED PORTION.	New	900.00
5	TO RUST PROOF THE AFFECTED AREAS.	New	180.00
Gross Labour Cost (S\$)			1,880.00

ComfortDelGro Engineering Pte Ltd/SJP8998R/08/05/2023 13:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >