

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : OH BOON TONG
BLK 610 ELIAS
#07-168
SINGAPORE (510610)

Not Authorized
1 Bl, 1 Pay @
2 days

Estimate No: MCS1900890
Date: 08 May 2023
Policy No: MA025573
Veh Reg No: SGJ37J
Make/Model: BMW 530I

ATTN:
Your Ref No: SGJ37J
Claim Type: Third Party
Accident Date: 07/05/2023

Estimate Repair Cost to Vehicle No :SGJ37J

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 HEADLAMP RH	1 PC	5,109.72	✓
2 FOG LAMP CHROME GARNISH RH	1 PC	90.20	X
3 RADIATOR GRILLE RH	1 PC	249.55	✓
4 FRONT BUMPER INNER SPONGE	1 PC	106.15	✓
		5,555.62	
	Less 5%	277.78	5,277.84
LABOUR			
5 TO CHECK WIRING AND REFOCUS HEADLAMP	1 PC	30.00	201
6 TO DISMANTLE AND REPLACE DAMAGE PARTS, TO REFIT AND ALIGN FRONT BUMPER AND HEADLAMP	1 PC	500.00	200
7 TO SPRAY FRONT BUMPER	1 PC	400.00	250
		930.00	930.00
Total			S\$ 6,207.84
Add GST @ 8%			496.63
Total Amount Payable			<u>S\$ 6,704.47</u>

TOTAL: SINGAPORE DOLLAR SIX THOUSAND SEVEN HUNDRED AND FOUR AND CENTS FORTY SEVEN ONLY

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
(SIN MING BRANCH)

176, Sin Ming Drive, #05-12

Sin Ming Autocare, Singapore 575721

Tel: 6456 3637 Fax: 6456 3686

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: