

Date: 3/5/2023
Vehicle No: SMU4002D
Model: HYUNDAI ACCENT (RB) 1.4 CVT
Chassis: KMHCU41BTKU481917
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLT876S
Date of Accident: 1/5/2023
Estimator: SIMON KOH

*Not Authorised
Surveyor: LK Kenneth
Penny BQ pain
Jelay*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET ASSY	1	\$ 1,282.00	\$ <i>Ry</i> 1,282.00
2	FRONT BONNET HINGE LH	1	\$ 55.00	\$ <i>Ry</i> 55.00
3	FRONT BONNET HINGE RH	1	\$ 55.00	\$ <i>0.1</i> 55.00
4	FRONT BUMPER COVER	1	\$ 477.00	\$ <i>Tu</i> 477.00
5	FRONT FOG LAMP LH	1	\$ 199.00	\$ <i>Mr</i> 199.00
6	FRONT BUMPER ENERGY ABSORBER	1	\$ 115.00	\$ <i>CM</i> 115.00
7	FRONT BUMPER REINFORCEMENT	1	\$ 300.00	\$ <i>Ry</i> 300.00
8	FRONT BUMPER UPPER STIFFENER ASSY	1	\$ 112.00	\$ <i>CM</i> 112.00
9	FRONT BUMPER SIDE RETAINER LH	1	\$ 25.00	\$ <i>CM</i> 25.00
10	FRONT FENDER ASSY LH	1	\$ 1,289.00	\$ <i>Ry</i> 1,289.00
11	FRONT FENDER INSULATOR LH	1	\$ 77.00	\$ <i>Tu</i> 77.00
12	FRONT FENDER MOUNTING BRACKET LH	1	\$ 30.00	\$ <i>Ry</i> 30.00
13	FRONT WHEEL GUARD LH	1	\$ 78.00	\$ <i>CM</i> 78.00
14	FRONT HEADLAMP ASSY LH	1	\$ 844.00	\$ <i>Ry</i> 844.00
15	FRONT SIDE MEMBER ASSY LH	1	\$ 1,552.00	\$ 1,552.00
16	FRONT FENDER APRON PANEL ASSY LH	1	\$ 289.00	\$ 289.00
17	FRONT TOP COWL COVER ASSY	1	\$ 228.00	\$ <i>CM</i> 228.00
18	FUSE BOX TOP COVER	1	\$ 33.00	\$ 33.00
20	FRONT ENGINE ROOM WIRE HARNESS	1	\$ 1,923.00	\$ 1,923.00
21	FRONT SHOCK ABSORBER LH	1	\$ 264.00	\$ <i>Ry</i> 264.00
22	FRONT AXLE KNUCKLE LH	1	\$ 382.00	\$ <i>Ry</i> 382.00
23	FRONT WHEEL HUB BEARING LH	1	\$ 144.00	\$ <i>Ry</i> 144.00
24	FRONT WHEEL HUB ASSY LH	1	\$ 199.00	\$ <i>Ry</i> 199.00
25	FRONT STABILIZER LINK LH	1	\$ 89.00	\$ 89.00
26	FRONT LOWER ARM ASSY LH	1	\$ 260.00	\$ <i>Ry</i> 260.00
27	FRONT AXLE CROSSMEMBER ASSY	1	\$ 1,348.00	\$ 1,348.00
28	FRONT DRIVE SHAFT ASSY LH	1	\$ 990.00	\$ 990.00
SUB TOTAL				\$ 12,639.00
LESS 20%				-\$ 2,527.80
PARTS TOTAL				\$ 10,111.20

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 551500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1983

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 560047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011



Date: 3/5/2023
Vehicle No: SMU4002D
Model: HYUNDAI ACCENT (RB) 1.4 CVT
Chassis: KMHCU41BTKU481917
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLT876S
Date of Accident: 1/5/2023
Estimator: SIMON KOH
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1	\$ 50.00	\$ 50.00
2	TYRE 215/45ZR17	1	\$ 145.00	\$ 145.00
3	FRONT WHEEL RIM 17"	1	\$ 350.00	\$ 350.00
			S/N TOTAL	\$ 545.00

LABOUR CHARGES:

LABOUR TO REMOVE, REPLACE/REPAIR, REALIGN AND REFIX THE LISTED ACCIDENT AFFECTED DAMAGED PARTS \$ 1,000.00

LABOUR TO REMOVE, REPLACE AND REFIX FRONT LH UNDERCARRIAGE ACCIDENT DAMAGED PARTS \$ 200.00

LABOUR TO REMOVE, REPLACE & REFIX FRONT LH WHEEL RIM AND TYRE (BALANCING) \$ 50.00

LABOUR TO PERFORM COMPUTERISED WHEEL ALIGNMENT \$ 120.00

LABOUR TO CHECK AND RECTIFY FRONT ENGINE ROOM WIRE HARNESS SYSTEM IN PROPER WORKING CONDITION \$ 150.00

LABOUR TO PUTTY, RESPRAY AND POLISH FRONT BUMPER, FRONT LH FENDER, FRONT BONNET, FRONT SIDE MEMBER ASSY, FRONT DOOR LH AND OTHER ACCIDENT AFFECTED AREA \$ 1,000.00

TO TUFF KOTE AND UNDERSEAL MATERIALS \$ 180.00

LABOUR TOTAL \$ 2,700.00

Simon TOTAL \$ 13,356.20

Head office

6 Kung Chong Road Singapore 160143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Aiyer Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

