JOYSKER WORKS

VEHICLE NO.: SJT9992D

VEHICLE MAKE/MODEL: BMW 530i

YOUR INSURED VEHICLE NO.: SHA9419S TO: (MOTOR CLAIMS DEPARTMENT)

THIRD PARTY CLAIMS

ACCIDENT DATE/TIME: 07/05/23@2030HRS

PARTS LIST

1	FRONT BUMPER
2	FRONT BUMPER SIDE RETAINER RH
3	FRONT HEADLAMP RH
4	FRONT HEADLAMP LOWER BRACKET RH
5	FRONT FENDER RH
6	FRONT FOG LAMP GARNISH RH
7	FRONT FOG LAMP RH

- 8 FRONT GRILLE CHROME MOULDING
- 9 FRONT BONNET
- 10 FRONT PARKING SENSOR Ferrity

S/NETT

1	FRONT BUMPER CLIPS SET
2	FRONT HEADLAMP CLIPS SET
3	FRONT FENDER CLIPS SET

LABOUR

FOR PANEL BEATING
FOR SPRAY PAINTING
FOR LIGHTING CHECK AND WIRING
FOR WATER TEST OF ACCIDENT PORTION
FOR REMOVE AND REFIX FRONT PARKING SENSOF
FOR DIAGNOSTIC CHECK AND RESET

DRICE ICY

PRICE (\$)			
\$ 1,680.90 301			
\$ 110.20?			
\$4,780.20 000			
\$ 221.95 ?			
\$1,260.40 pert			
\$ 260.30 cra			
\$ 190.40 ?			
\$ 430.50?			
\$ 2,680.20			
\$ 285.10			
\$11,900.15			
\$ 595.01			
\$11,305.14			

\$ 80.00 wec
\$ 60.00 NIC
\$ 60.00 mes
\$ 200.00

-5%

\$	1,400.00 400
\$	1,200.00 400
\$	100.00 30
\$	80.00 🗶
\$	120.00 3 0
\$	380.00 🗶
\$	3,280.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

4 desgs 9/5/23 L/S 2pm / 11/hn 70047659