



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

TP111

Xiao Tong.

Vehicle No. SMF397U

TOYOTA ALLION

NZT2603032663

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT BUMPER <i>Dehd</i>		1210.10	✓
2	FRONT BUMPER SIDE HOLDER @53.70 <i>Neu</i>		107.40	+
3	FRONT BUMPER REINFORCEMENT <i>Dented</i>		295.60	✓
4	FRONT BUMPER LOWER GRILLE <i>Crushed</i>		201.20	✓
5	FRONT BUMPER FOG LAMP @272.20 <i>Neu</i>		544.40	+
6	FRONT BUMPER FOG LAMP COVER @59.30 <i>Neu</i>		118.60	+
7	FRONT BUMPER SPONGE <i>Crushed</i>		105.70	✓
8	FRONT GRILLE <i>Crushed</i>		361.90	✓
9	FRONT GRILLE LOGO <i>Neu</i>		50.10	✓
10	HEADLAMP @659.60 <i>Crushed</i>		1319.20	✓
11	FRONT BRACE PANEL <i>Best</i>		98.50	✓
12	BONNET <i>Rips</i>		1009.90	+
13	BONNET LOCK <i>Neu</i>		85.10	+
14	FRONT SUPPORT PANEL <i>Rips</i>		911.50	+
15	HORN @52.10 <i>Neu</i>		104.20	+
16	AIR CON CONDENSER <i>Dented</i>		1333.10	✓
17	RADIATOR <i>Neu</i>		1610.20	X
18	RADIATOR TOP COVER <i>Crushed</i>		121.20	✓
19	RADIATOR FAN COWLING		244.30	X
20	RADIATOR FAN BLADE		145.80	X
21	RADIATOR FAN MOTOR		466.30	+
22	RADIATOR SPARE TANK		65.40	+
23	RADIATOR TOP HOSE		105.20	+
24	REAR NUMBER PLATE LAMP @51.70 <i>Neu</i>		103.40	+
25	REAR BUMPER <i>Dented</i>		1248.30	✓
26	REAR BUMPER SIDE HOLDER @73.80 <i>Neu</i>		147.60	+
27	REAR BUMPER REFLECTOR @56.60 <i>RH crushed</i>		113.20	56.60
28	REAR BUMPER IMPACT BRACKET @63.20 <i>Dented</i>		126.40	✓
29	REAR END PANEL <i>Dented</i>		867.90	✓
30	REAR END PANEL TOP GARNISH <i>Dehd</i>		265.30	✓
31	REAR END PANEL ANTENNA LOCK <i>Crushed</i>		147.40	✓
32	TAILLAMP @425 <i>Crushed</i>		850.00	✓
33	TAILLAMP PANEL @175.40 <i>Dented</i>		350.80	✓
34	BOOTLID <i>Dented</i>		950.90	✓
35	BOOTLID LOCK <i>Long</i>		323.40	✓
36	BOOTLID WEATHERSTRIPE <i>wt</i>		189.30	✓
37	BOOTLID HINGE @131.80		263.60	+
38	BOOTLID HINGE COVER @88.50 <i>3 x Neu</i>		177.00	+
39	BOOTLID INNER TRIM <i>Neu</i>		295.10	+
40	BOOTLID OUTER CHROME MOULDING <i>Neu</i>		292.80	+
41	TOYOTA LOGO <i>Neu</i>		70.20	✓
42	REAR FENDER @981.10 <i>RH Buckled</i>		1962.20	981.10
43	REAR FENDER INNER TRIM @329.10 <i>RH torn</i>		658.20	329.10
44	REAR FENDER INNER SHIELD @85.90 <i>Neu</i>		171.80	+
45	REAR WINDSCREEN MOULDING <i>Neu</i>		158.50	✓

46	SPARE TYRE PANEL	<i>Pyir</i>	960.60	<i>+</i>
47	SPARE TYRE PANEL TOP COVER	<i>men</i>	292.80	<i>+</i>
48	REAR EXHAUST PIPE	<i>2</i>	998.10	<i>+</i>
49	REAR EXHAUST PIPE MOUNTING	<i>HP</i>	35.60	<i>+</i>
50	REAR EXHAUST PIPE GASKET	<i>men</i>	32.90	<i>+</i>
51	REAR EXHAUST HEAT SHIELD		165.30	<i>+</i>
			22833.50	
less 25%			5708.38	25%
			17125.13	
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE	<i>ambd</i>	30.00	<i>-</i>
2	FRONT NUMBER PLATE HOLDER	<i>ambd</i>	30.00	<i>-</i>
3	FRONT BUMPER CLIPS	<i>men</i>	30.00	<i>✓</i>
4	FRONT GRILLE CLIPS		20.00	<i>✓</i>
7	COOLANT	<i>men</i>	50.00	<i>✓</i>
8	REAR NUMBER PLATE	<i>men</i>	30.00	<i>+</i>
9	REAR NUMBER PLATE HOLDER		30.00	<i>+</i>
10	REAR BUMPER CLIPS	<i>men</i>	50.00	<i>✓</i>
11	REVERSE SENSOR	<i>ambd</i>	280.00	<i>200</i>
12	REAR CAMERA	<i>men</i>	480.00	<i>+</i>
13	REAR END PANEL TOP GARNISH CLIPS	<i>men</i>	20.00	<i>✓</i>
14	REAR END PANEL SEALANT	<i>men</i>	60.00	<i>✓</i>
15	BOOTLID INNER TRIM CLIPS	<i>men</i>	30.00	<i>+</i>
16	BOOTLID OUTER CHROME MOULDING CLIPS	<i>men 580</i>	20.00	<i>+</i>
17	REAR WINDSCREEN SEALANT	<i>men</i>	60.00	<i>✓</i>
18	REAR FENDER INNER TRIM CLIPS	<i>men</i>	60.00	<i>30</i>
19	REAR FENDER INNER SHIELD CLIPS	<i>men</i>	20.00	<i>+</i>
20	SPARE TYRE PANEL INSULATION PADS	<i>men</i>	280.00	<i>+</i>
Total Parts			1580.00	



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Vehicle No. SMF397U

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	PANEL BEATING	3000.00	1800
2	SPRAY PAINTING	2800.00	1800
3	WIRING	100.00	60
4	TO APPLY TUFF COAT	250.00	100
5	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	120.00	60
6	TO REMOVE RADIATOR & TO TOP UP COOLANT	120.00	60
7	TO REMOVE UPHOLSTERY	150.00	65
8	TO TRANSFER BOOTLID FITTINGS	150.00	60
9	TO REMOVE REAR WINDSCREEN	180.00	120
10	TO REMOVE REVERSE SENSOR	100.00	50
11	TO REMOVE REAR CAMERA	100.00	50
12	TO REMOVE FUEL TANK	150.00	X
13	TO REMOVE REAR EXHAUST PIPE	150.00	X
	Labour Total :	7370.00	
TOTAL (PARTS & LABOUR):		26075.13	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
2/s 09/05/23.

15 Days.

total: 13808.85

4/s: 6.4k.
(Nett Value)

Nett Value